

1 602	- N67 11396	
ITY FORM	(PAGES)	(THRU)
FACIL	NASA CR OR TMX OR AD NUMBER	(CODE)
	CR- 79092	(CATEGORY)

GPO PRICE \$	•
CFSTI PRICE(S) \$	-
Hard copy (HC) 400 Microfiche (MF) 100	-
ff 653 July 65	

Beech Aircraft Corporation

BOULDER, COLORADO U. S. Q.



BEECH AIRCRAFT CORPORATION

Boulder Division

TEST REPORT

No. FR 13632 Date 11/25/614	Rev.	Dates Revised
FINAL TEST REPORT FOR LIQUID HYDROGEN PRESSURIZATION TESTS	A	5/5/ 65

Contract No. NAS8-5331

Customer:

National Aeronautics and Space Administration

George C. Marshall Space Flight Center

Huntsville, Alabama

Period Covered: 29 May 1963 - 27 August 1964

APPROVAL SIGNATURES	DATE
Prepared by: Allat 12 Louril A. R. Lowrie, Test Engineer	6 MAY 65
T. Bielewski, Group Engineer	6 MAY 65
J. R. Maboitt, Assistant Manager	

ENVIRONMENTAL TEST LABORATORIES

Boulder, Colorado

Beech Aircraft Corporation — Environmenta: Test Laboratories

Document No.	Rev	Page
FR 13632	A	11
Issue Date	Revision	on Dates
11/25/64	'A"	5/5/6 5

TABLE OF CONTENTS

Paragraph		Page	
	MTMT DAGE		-x., 4, 6, 6, 5
	TITLE PAGE	i	
	TABLE OF CONTENTS	ii	
	ADMINISTRATIVE DATA	1.0	
1.0	INTRODUCTION	2.0	
2.0	CHRONOLOGICAL PROGRAM HISTORY		
3.0	TEST PROCEDURE	16.0	
4.0	TITANIUM TANK INFORMATION	17.0	
5.0	EXTERNAL HEATING PROGRAM	20.0	
6.0	LIQUID HYDROGEN GAS DIFFUSER	26.0	AVE.
7.0	FAST RESPONSE THERMOCOUPLE DEVELOPMENT	29.0	
ė.o	DATA PROGRAM	27.0	•
9.0	Test results suppary		
Appendices			
Whengrees			
A	NASA Pressurization Study Run Sequence	74.0	
B .	Propellant & Pressurization Schematic - Thermal	•	i i i
	Test Facility	76.0	
C	Pressurization Control System Schematic	78.0	
D	Thermal Test Facility Photographs	80.0	- 91.0
E	Test Equipment List		94.0
7	Instrumentation Locations	96.0	
G	Instrumentation Channel Assignments		- 104.0
H	Properties of 6Al-4V Titanium	-	- 112.0
Ī	Bristol Temperature Recorders Calibration	200.0	 • •
	Curves	114.0	- 128.0
J	Flowmeter Calibration Curves		- 134.0
K	NASA-Supplied Test Curves	136.0	۵,٠
- -		4	

Beech Aircraft Corporation — Environmental Test Laboratories

FR 13632

Rev Page

A 1.0

Issue Date Revision Dates

11/25/64

Revision Dates

ADMINISTRATIVE DATA

Purpose of Test:

To supply pressurization data which will be used to assist in heat exchanger design

for the Saturn Missile Program.

Test Specimen:

7000 Gallon 6Al-4V Titanium Test Tank

Manufacturer:

Beech Aircraft Corporation, Boulder, Colorado

Number of Tests Conducted:

Sixteen (16)

Tests Conducted by:

A. R. Lowrie, Test Engineer Beech Aircraft Corporation Liquid Hydrogen Test Facility

Boulder, Colorado

Disposition of Test Specimen:

The 7000 gallon titanium test tank was destroyed during a test run on 27 August 1964. The Beech Aircraft Corporation is presently awaiting the Government directions as to disposition of the test tank remains.

Abstract:

In accordance with Beech Aircraft Corporation—Work Order No. 32100, a series of liquid hydrogen pressurization tests was conducted, utilizing the titanium test tank in the thermal test tower vacuum bell. These tests consisted of helium and hydrogen gas for pressurization with four (4) tests including the application of external heat flux.

Beech Aircraft Corporation — Environmental Test Laboratories

| Page |

2 4 to 2 a 6

FINAL TEST REPORT FOR LIQUID HYDROGEN PRESSURIZATION TESTS

INTRODUCTION - The purpose of the tests described in this document is to satisfy the requirements of Beech TP 13636-3 to conduct liquid hydrogen pressurization tests for the Fluid Mechanics and Thermodynamics Branch of NASA Marshall Space Flight Center, Huntsville, Alabama.

2.0 CHRONOLOGICAL PROGRAM HISTORY

May 29 - Negotiated Contract No. NASS-5331 with National Aeronautics and Space Administration at the George C. Marshall Space Flight Center, Huntsville, Alabama. The Contract was for conducting a series of liquid hydrogen pressurization tests in the Beech Aircraft Corporation's Boulder Division, Thermal Test Facility. Program completion was set at one year from the Contract date.

June 24 - Substituted the 7000 gallon titanium test tank for the stainless steel test tank, which was shipped to its rightful owner, Edwards AFB, California.

July 19 - Received the first budget authorization for W.O. 82100 NASA Contract NAS8-5331. This included Series "A" testing only.

July 25 - Received supplement #1 to the budget authorization. This supplement to provide for procuring and buildup of the 100 point liquid level indicating system.

July 28 - Submitted drawing of the titanium test tank instrumentation rake.

August 1 - Initiated purchase order for forty (40) Germanium thermometers, calibrated from 20°K to 40°K with an accuracy of ±0.3% above range. The nominal resistance at 40°K will be 10 ±1 ohms and at 20°K will be 35 ±1.5 ohms.

August 26 - Problems were encountered in the contractual requirements for a fast response temperature measurement probe capable of 62.3% of the total temperature change, in two seconds or less, in still air. NASA supplied drawings and test data of a probe used in liquid oxygen, which could meet this requirement.

August 27 - Submitted drawing No. 60358, Liquid Hydrogen Gas Diffuser, to NASA for approval.

September 23 - Received the fast response thermocouple drawings and test data sheet from NASA.

Beech Aircraft Corporation — Environmental Test Laboratories

FR 13632 A 3.0

Issue Date Revision Dates
11-25-64 "A" 5/5/65

September 25 - Decision is made that Beech personnel will fabricate and test the fast response thermocouples to be used on this program.

October 8 - Designed a prototype fast response thermocouple and submitted both drawing No. 60377 and the model to NASA for approval.

October 31 - Issued Engineering for the following:

- a. Liquid Hydrogen Gas Diffuser
- b. Propellant System Interconnections
- c. Pressurization and Vent Systems Interconnections
- d. Instrumentation Interconnections

December 14 - Changed the Germanium Thermometer nominal resistance to 7.5 ±1 ohms at 40 K and 35 ±1.5 ohms at 20 K.

December 26 - Completed the fabrication of a new instrumentation Rake to be used in the Titanium Tank.

December 29 - Installed an Antivortex Baffle in the Titanium Test Tank.

December 30 - Completed the fabrication of 40 fast response thermocouples per NASA specifications. Installed five of these in the NAA Saturn II tank for evaluation purposes, and to determine how well the commutating system would function in conjunction with thermocouples, without amplifiers.

December 31 - Received the fabricated liquid hydrogen gas diffuser and all of the interconnecting spool pieces from manufacturing. Installed the diffuser in the test tank.

January 2 - Started calibration and testing of the fast response thermocouples. The millivolt output was very wide spread in both liquid nitrogen and liquid hydrogen. Data to be presented to NASA in order to determine the procedural variations.

January 19 - Received the first twelve (12) Germanium probes to be used in the test program. The respective calibration curves were included.

January 20-21 - A trip to Huntsville, Alabama was made to establish a clarification of program objectives. Items of discussion included the following itinerary:

- a. Program Objectives
- b. Testing Sequence
- c. Titanium Test Tank and Properties
- d. Vortexing Possibilities
- e. Instrumentation Locations

Beech Aircraft Corporation — Environmental Test Laboratories

- f. Pre-Pressurization Procedure
- g. Pressurization and the Liquid Hydrogen Gas Diffuser
- h. Monthly Progress Reports
- i. Recording Sequence
- j. A Test Procedure Review
- k. Liquid Level System

A meeting was held with the testing personnel on their procedure for the fast response thermocouple calibration. Several factors which might be affecting our thermocouple accuracy were discussed.

January 29 - Revised the heat tower pressurization control system to allow a flow of gas only when the ullage pressure drops below the required operating pressure. This was accomplished by using a pressure switch to control the test tank pressurization control valve.

January 30 - Released the revised test procedure, TP-13632-3, for series "A" testing.

January 30 - Completed the cleaning of the titanium test tank.

January 31 - Conducted a leak check of the titanium test tank.

January 31 - Fabricated the instrumentation cover plate for thirteen (35 Pin) amphenol connectors and for three (37 Pin) copperconstantan connectors.

Pebruary 3 - Submitted Progress Report for January.

February 5 - Completed the addition of another arm to the instrumentation rake.

February 11 - Contracted for a data reduction program which will enable Beech personnel to reduce data from MTA-2 magnetic tape through the use of the G-15D computer.

February 15 - Completed the fabrication of the instrumentation cover plate and connecting leads.

February 17 - Completed modifications to the pressurization and vent system in order to utilize the same flowmeter and provide larger flow rates.

February 19 - The University of Colorado calibrated the vent and pressurization flowmeter to provide flow rates in both directions.

Beech Aircraft Corporation — Environmental Test Laboratories

FR 13632 Revision Dates
11-25-64 Revision Dates

February 25 - Revised the series "A" test schedule due to the NAA Saturn II test program.

February 27 - The five fast response thermocouples in the Saturn II test tank indicated, but time data could not be verified.

February 27 - Received the balance of the Germanium probes which were ordered for the test program.

February 29 - Fabricated a cryostat to be used for the fast response thermocouple tests and calibration.

March 1 - Submitted Progress Report for February.

March 6 - Completed the installation of teflon brackets on the instrumentation rake.

March 9 - Completed the revised instrumentation print for NASA review.

March 11 - Procured a 48 channel copper-constantan automatic thermocouple reference system (ice point) to be used in thermocouple testing and in the test program.

March 11 - M. Nein, NASA Technical Supervisor, visited the Boulder Facility to observe preparations to testing and to discuss the following itinerary:

- a. Magnetic Amplifiers and Isolation Transformers to be used with the Fast Response Thermocouples
- b. Liquid Level Locations on the Instrumentation Rake
- c. Installation of Three Temperature Probes on the Diffuser
- d. Revising the Test Schedule
- e. Discuss the Possibility of Two Additional Helium Runs
- f. Discuss Possibility of Obtaining Helium Samples During Run.

Merch 13 - Conducted a computer program of height versus volume in the titanium test tank.

March 14 - Submitted curves of titonium properties to NASA.

March 15 - Completed the instrumentation rake wiring.

March 19 - Ordered forty Model 190 Magnetic Amplifiers and isolation transformers. Beech representative to observe equipment and return with two models to Boulder for preliminary testing.

Beech Aircraft Corporation — Environmental Test Laboratories

FR 13632 A 6.0

Issue Date Revision Dates
11-25-64 "A" 5/5/65

March 31 - Installed a three-way ball valve to enable faster changeover from pre-pressurization to pressurization.

April 1 - Submitted Monthly Progress Report for March.

Released revised Series "A" test schedule.

Drafted fast response thermocouple test procedure.

Contacted the National Bureau of Standards for information regarding the obtaining of helium samples during the test runs. Availability of equipment for analysis was a problem and doubt was expressed as to results which would be obtained.

April 3 - Completed the cryostat test setup for the fast response thermocouple calibration.

April 6 - Contacted by NASA on following subjects:

- a. Requested One Run of the Coldest Possible Helium for Pre-Pressurization
- b. Photographs of the Diffuser
- c. Status of the Two Additional Helium Runs
- d. Magnetic Amplifier Status
- e. Date for Start of Testing

Started the fast response thermocouple calibration and response test.

Modified the cryostat to prevent probes from contacting sidewalls. Installed a limit switch.

April 7 - Thermocouple Calibration and Response Test. The wires broke on the moving parts inside of the cryostat. They had to be run through the movable tubing. The reference probe and the test probes had to be located closer together.

Tested a teflon frame probe (T-7) with a peaked junction. Response very good.

April 8 - Conducted a 40 psia static proof pressure test with gaseous nitrogen on the titanium tank. Results satisfactory.

Thermocouple Testing: Conducted tests on T-8 and T-6 probes. Results were not good. Repeated tests on T-7 with good results.

April 9 - Thermocouple Testing:

- a. Fabricated a new liquid level indicator for the cryostat.
- b. Modified reference probe in order to immerse it in the test media.
- c. Tested some thermocouples to determine effect of peak pointing up, pointing down, and the frame of a variable width.

The state of the s

Received the new 32°F reference oven and installed it in the test setup.

FR 13632 A 7.0

April 10 - Thermocouple Testing: Redesigned the cryostat to correct several problems. Installed two microswitches to supply a trace of the probe travel in and out of the liquid. A support arm was installed to allow smoother operation during probe travel.

Conducted tests on four probes which had not been tested previously.

April 13 - Received the new COX propellant flow mater. Installed the two pressurization valves for the new pressurization system.

Thermocouple Testing: Tested the effect of insulation and varnish on the junction wire of several probes. Fabricated an 18-gauge stranded wire as a frame and tested this. Started testing with the probe junction at various angles to the horizontal. Response extremely poor.

April 14 - Thermocouple Testing: Tested seventeen (17) thermocouples with varying junctions to evaluate the effect upon response.

Contacted the National Bureau of Standards for additional information on the feasibility of helium samples during test runs. Subject included cost of sample analysis and time to accomplish the task.

April 15 - Thermocouple Testing: Fabricated several thermocouples using a solid 20 gauge copper-constantan wire for the frame and 30 gauge for the junction. Response tests were very good so it was decided to test these extensively. Test Procedure involved changing the angle of the junction, shortening the distance between the yoke arms, and varying the angle of the junction with the horizontal during testing.

April 16 - Installed the sixteen (16) skin temperature thermocouples to the outside of the titanium test tank.

Started to install the test tank in the vacuum bell, but were unable to do so due to the wind.

Repaired the thermocouple cable to the vacuum bell for the heat rate computers.

April 17 - Installed the titanium test tank in the heat tower vacuum bell.

Installed the Cox Propellant Flowmeter in the outflow line.

Installed the waugh vent and pressurization flowmeter.

Installed elbows on the titanium tank inlet ports.

Continued thermocouple testing for the effect of the speed of probe travel on removal from liquid to gas.

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. Rev Page
FR 13632 A C.O

Issue Date 11-25-64

Revision Dates
"A" 5/5/65

April 20 - Installed the propellant fill line to the test tank.

Checked out pressurization system valve operations.

Thermocouple Testing: Tested a 1" square frame, a 2", and a 3" model thermocouple. The 3" square model provided the best results. Ran an additional series of tests on this model with very good results. Decided this was the type we would use for the test tank internal temperatures. Started fabrication of forty-five (45) thermocouples of this type.

April 21 - Thermocouple Testing: Continued the testing of our production type thermocouple through various angles at various velocities. Started the official calibration of seven (7) of the forty-five production models. Completed with good results.

April 22 - Completed the fabrication of the forty-five production type thermocouples to be used in the test tank.

April 23 - Prior to final calibration it was decided that the procedure would be to take three (3) millivolt readings and series of ten (10) response tests on each probe.

April 24 - Contacted NASA as to the following information:

- a. Pressurization requirements NASA to send the pre-pressurization and pressurization gas temperatures required for the first series of runs.
- b. NASA to conduct the helium solubility tests in their own battleship program.

Inreased the pre-pressurization gas heat exchanger by an additional 100 feet of copper tubing.

Calibrated eleven (11) of the fast response thermocouples (Production Type).

April 27 - Calibrated eight of the fast response thermocouples.

April 28 - Installed new l" line for helium pre-pressurization.

April 29 - Calibrated six of the fast response thermocouples. Continued work on the helium system.

April 30 - Completed the calibration of the remaining fast response thermocouples in liquid nitrogen.

Installed the vent line to the titanium tank.

Installed helium lines to the control panel.

Beech Aircraft Corporation — Environmental Test Laboratories

11-25 -64		n Dates A" >/5/65
rR 13632	A	9.0
Document No.	Rev	Page

May 1 - Completed a rerun calibration of the first 14 fast response thermocouples in liquid nitrogen.

Started converting cryostat to liquid hydrogen capability.

May 4 - Encountered problems in liquid hydrogen calibration of fast response thermocouples. Conducted runs at 8 psig, 18 psig, and 38 psig. Data was erroneous.

May 5 - Modified cryostat vent system and installed a pressure switch to control pressure to ±1/2 psig. Reading still not satisfactory. Bypassed the copper-constantan connector and readings were good. Ran all leads through the cover and made connections outside of the cryostat.

May 6 - Encountered many leaks when the cryostat was pressurized. Drilled holes for the thermocouple leads and epoxied around each wire.

May 7 - Still encountered leakage around wires. Decided the leakage was coming through the insulation. Stripped the insulation off and epoxied between wire and cryostat cover. Leakage was eliminated. Completed the magnetic amplifier chassis buildup.

May 8 - Conducted the liquid hydrogen calibration on test thermocouples 1 through 10 at 12, 20, 30, 40 and 50 psia.

May 11 - Calibrated fast response thermocouples 11 through 22 in liquid hydrogen. Stabilized thirty minutes between each change in pressure and one minute between each millivolt reading.

May 12 - Calibrated thermocouples 23 through 33.

Fabricated brackets for installation of instrumentation on titanium tank internal walls.

May 13 - Calibrated Leeds & Northrup potentiometer prior to completing thermocouple calibration.

Completed wiring to the magnetic amplifiers.

May 14 - Installed instrumentation brackets to the internal wall of the test tank.

Installing 30-channel events recorder for liquid level indicating system. Received authorization to:

- a. add two additional helium pressurization tests to the program,
- b. modify two of the present series "A" tests, and
- c. extend the contract until 30 September 1964.

Beech Aircraft Corporation — Environmental Test Laboratories

FR 13632

Rev Page

A 10.0

Issue Date

11-25-64

RevIsion Dates

5/ 5/ 5/ 5

May 15 - Installed all instrumentation and wiring to the internal wall of the test tank.

Calibrated fast response thermocouples 34 through 45.

Installed the vent and pressurization line to the vacuum bell and to the titanium test tank.

Installed the vacuum bell dome over the test tank.

May 18 - Installed fast response thermocouples to the instrumentation tree.

May 19 - Continued work on the new pre-pressurization system and the instrumentation rake.

May 20 - At the request of NASA, a technical and administrative visit was made to Huntsville, Alabama. Topics of discussion included:

- a. Costs of Proof Pressure Testing the Titanium Tank
- b. Refund Associated with Platinum Probes
- c. Finalize the Four Pending Contract Modifications
- d. Costs Incurred to Date Versus Technical Performance
- e. Start Date for Testing
- f. Additional costs that can be Expected to be Incurred on the Program

Installed pressure regulator in the pre-pressurization system.

Installed thermocouple wires for test tank hookup.

May 21 - Completed installation of Germanium probes on the instrumentation tree.

Terminated ends of the thermocouple multiconductor cable.

Wiring installed to all new valving.

May 22 - Installed Germanium probe and a fast response thermocouple in the test tank outflow line.

Completed the pre-pressurization system to the third level of the tower.

Installed wiring between the patch panel and the magnetic amplifiers.

May 25 - Installed the instrumentation rake in the test tank.

Installed the thermocouple and pressure transducer in the pre-pressurization system.

Continued wiring effort for remote test operation.

May 26 - Installed flowmeter in the pre-pressurization system.

Installed the instrumentation cover plate on the vacuum bell.

TONGER OF THE

FR 13632 A 11.0

Repair damaged thermocouples on the instrumentation tree. Completed all magnetic amplifier wiring.

May 27 - Completed the hookup of all internal wiring to the instrumentation tree.

Modifying control panel to accommodate new valving.

Completed the circuit for the input to the 30-channel events recorder. Completed the hookup of all thermocouple leads to the reference oven.

May 28 - Completed allwork in the test tank.

Installed the ullage pressure readout line.

Installed diffuser with 3 fast response thermocouples in the test tank.

May 29 - Prepared instrumentation patch sheet with associated instrumentation locations in the test tank.

Completed the relay panel and installed in the control console.

Completed the installation of the pre-pressurization system.

Completed installation of the pressurization 3-way valve.

Calibrated the three pressure transducers.

June 1 - Submitted Monthly Progress Report.

Ordered helium tube trailer.

Completed all work on the liquid level indicating system.

Commenced with the instrumentation checkouts.

June 2 - Installed the titanium tank manhole cover and started all systems leak checks.

Installed vacuum bell cover.

All systems checkout complete.

June 3 - Started the vacuum pumpdown.

Conducted the liquid nitrogen fill and drain checkout; the following problems were encountered:

- a. Pressure switch set to psig rather than psia.
- b. Control to the pre-pressurization control valve needed to be reworked.
- c. The pre-pressurization regulator did not control properly.
- d. The liquid level indicating system required resetting.
- e. Changes necessary in the pressurization control system.

Beech Aircraft Corporation — Environmental Test Laboratories

Document No.	Rev	Page
FR 13632	A	12,0
11-25-64	Revisio	n Dates /5/65

June 4 - Corrected all problems encountered in the fill operation.

Conducted another liquid nitrogen fill operation.

June 4 - Discovered a leak in the vacuum jacket cover on the flow control valve.

Located leakage at the vent and pressurization flange on the vacuum bell.

Small leakage was evident on the instrumentation plate.

June 5 - Repaired all leaks.

All systems ready for the liquid hydrogen compatibility test. The liquid hydrogen due Sunday night.

Series "A" test run No. 1 scheduled for Wednesday, June 10.

June 8 - Received the liquid hydrogen as scheduled. Leakage developed on the No. 1 liquid hydrogen storage dewar at the burst disc. While personnel were repairing the leak, lightening struck the heat tower with a fire resulting. Two rluids mechanics were burned and extensive damage to the facility resulted. The liquid nitrogen delugacystem was used to control the fire.

June 9-12 - All liquid hydrogen was removed from the facility and an estimation of the damage was made. Plumbing on top of the storage dewars was badly burned as was most of the wiring in the storage wing. Twelve control valves had to be replaced. A large crack in the No. 2 storage dewar vacuum jacket resulted and required welding.

June 15 - July 22 - Rework of the facility to repair damage caused by the fire.

July 22 - Completed checkout of all systems in preparation of receiving liquid hydrogen.

July 23 - Received liquid hydrogen and conducted a liquid hydrogen compatibility test. Encountered several instrumentation problems. These areas were corrected and all systems made ready to start run No. 1 on Tuesday, July 23th.

July 27 - A bad electrical storm over the weekend burned up a transformer and the vacuum rump to the storage dewars. Power transferred to another transformer and the vacuum pump replaced. The liquid hydrogen due next day.

July 29 - The liquid hydrogen did not arrive until the end of the shift. Test scheduled for next day.

Beech Aircraft Corporation — Environmental Test Laboratories

FR 13632 A 13.0

Issue Date Revision Dates
11-25- 64 A 5/5/65

July 30 - Started the fill of the test tank for Run No. 1. The propellant flowmeter would not supply a readout. The test tank was drained and the flowmeter removed. A wire was grounded on the vacuum jacket. The flowmeter was reinstalled in the system and checked for a readout. Indications were good.

good.

July 31 - Conducted Series "A" test Run No. 1. Systems looked

August 3-9 - Reducing the test data from Run No. 1.

August 10-12 - Prepared test data to be sent to NASA. Started correcting some problems evident in this run.

- a. Pressurization and vent gas flow rate set for 750 to 1250 CFM. This problem was corrected.
- b. Liquid level indicators not playing properly.
- c. Problems with Channels 41 and 63.
- d. The three temperatures on Channels 83, 84 and 85 were not reading correctly.

August 13 - Replaced the teflon gaskets at the vent and pressurization gas flowmeter. Used Florablue instead of Teflon material. Conducted Series "A" Test Run No. 3.

August 14 - Instrumentation working a timing problem.

The cannon connectors on the instrumentation plate were damp and had to be dried out.

Conducted Series "A" Test Runs Numbers 4 and 6.

August 17 - Conducted the following test runs:

Series "A" Test Run No. 2

Series "D" Test Run No. 15

Series "D" Test Run No. 14

Series "A" Test Run No. 5

During run number 15 we could not maintain the 2100 GPM flow rate as required. With the propellant flow control valve wide open the flow rate was only 1650 to 1700 GPM.

August 18 - Conducted the following test runs:

Series "A" Test Run No. 7

Series "A" Test Run No. 6

Series "A" Test Run No. 4

During a preliminary check of the data it was noted that our propellant flow rate was increased by a factor of 2. Investigated problem.

Beech Aircraft Corporation — Environmental Test Laboratories

FR 13632 Rev Page

FR 13632 A 14.0

Issue Date Revision Dates
11-25-64 "A" 5/5/65

August 19 - Investigation of the problem indicated that we had a 75 millivolt reading at zero flow. Could not locate the cause, but during the trouble shooting of the system, the problem disappeared. Waited for liquid hydrogen in order to continue testing.

August 20 - Conducted Series "A" Test Run No. 6. The propellant flow rate was still too high. Further investigation revealed a manufacturer's ground was defective in the Foxboro flow controller. Due to the fact that this problem existed in the previous runs, it was decided to rerun all of the previous runs.

Conducted Series "A" Test Run No. 3. Run was good.

August 21 - Conducted the following test runs:

Series "A" Test Run No. 2 Run was good.
Series "A" Test Run No. 4 Run was good.
Series "A" Test Run No. 6 Run was good.
Series "D" Test Run No. 14 Run was good.

August 22 - Conducted the following test runs:

Series "A" Test Run No. 7

Series "A" Test Run No. 5

Good Run

Series "C" Test Run No. 11

Series "C" Test Run No. 12

Series "C" Test Run No. 13

Series "C" Test Run No. 13

Series "A" Test Run No. 7

Good Run

August 24 - In preparation to conducting the external heat flux runs, it was determined that the ignitrons in the ignitron power controllers No. 1 and No. 15 were no good. Replaced these with ignitrons from Controller No. 14.

August 25 - Conducted Series "E" Test Run No. 18. Good Run

August 26 - Conducted the following runs:

Series "E" Test Run No. 17 Good Run Series "E" Test Run No. 16 Good Run Series "F" Test Run No. 22 Good Run

Problems developed in the heat controller console so it was decided to proceed with the 50 psia proof pressure test of the titanium tank and then conduct the three 50 psia Series "B" tests.

August 27 - The titanium test tank was filled with liquid hydrogen and then the pressure increased to 50 psia. The tank was vented off after a stabilization period and the above operation repeated.

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. Rev Page
FR 13632 A 15.0

issue Date 11-25-64 Revision Dates
"A" 5/5/65

The test tank was then prepared for the first of the three Series "B" Test Runs. During pre-pressurization the operating pressure (50 psia) was reached in 48.7 seconds. After a 7.4 second stabilization the drain operation commenced. At T + 36.3 seconds the test tank ruptured dropping approximately 6000 gallons of liquid hydrogen into the vacuum bell. Extensive damage was caused to the vacuum bell and the heat lamp assemblies. The vacuum bell cover was blown off tearing the support plumbing throughout the tower. The liquid nitrogen deluge system was activated in the tower area and the possibility of a fire was controlled while the liquid hydrogen in the vacuum bell was vaporizing. The cause of rupture is unknown, but the data concluded that there was no over-pressurization.

August 28 - Air Force personnel conducted an investigation of the damage.

August 31 - Started removal of the test tank from the vacuum bell.

<u>September 1</u> - Removal of the test tank is complete. All work in the heat tower is stopped until further notice.

September 7 - Due to the length of time involved to reduce a test run on the Bendix G-15D Computer at Beech it was decided to transfer the data to an IBM tape for faster reduction.

September 12-13 - Started conversion of the present digital magnetic tape to an IBM Compatible Tape Format.

September 19-20 - Continued Tape Transfer

October 3-4 - Continued Tape Transfer

October 7 - Received all reduced data from NBS.

October 7-12 - Organizing and binding all data runs in separate folders.

October 12 - Delivered all data to Contracts Administration for delivery to NASA.

October 28-30 - In order to clarify some problem areas in the data and to finalize the existing contract, a trip was made to Huntsville, Alabama. The itinerary of this trip included:

- a. Test Data Terminology
- b. Titanium Tank Information
- c. Boiloff Rates
- d. Test Report
- e. Tour of NASA Battleship Facility
- f. Contractural Meeting

November 9 - Started writing Test Report.

Beech Aircraft Corporation - Environmental Test Laboratories

Document No. Rev Page
F R 13632 A 16.0

Issue Date 11-25 -64 Revision Dates
"A" 5/5/65

accomplished in the same manner, except for those requiring external heat application. The test tank was filled with liquid hydrogen until liquid level sensor No. 48 indicated a covered condition. A short time was allowed for the level to drop below this sensor and then pre-pressurization would begin. All recorders were turned on five (5) seconds prior to pre-pressurization and allowed to run until the drain operation was completed. Pre-pressurization was controlled by a pressure switch which would automatically close the PPC valve when the operating pressure was attained. At this time the PPC switch was manually actuated in order to hold the valve closed and to switch the automatic control to the main pressurization flow control valve (PFC). The parameter for pre-pressurization was 50 to 80 seconds, which was followed by a stabilization period of 20 seconds maximum.

The drain operation was started by simultaneously opening the fuel flow control valve, FFC, and turning the pressurization valve, PV, to the tank position. Prior to this time the pressurization valve had been turned to the vent position in order to bring pressurant gas up to the required operating temperature. Propellant flow was controlled by a Foxboro flow indicating system which was manually operated to the desired flow rate.

Pressurization during the drain operation was automatically controlled by the ullage space pressure switch. This switch actuated the pressurization flow control valve, PFC, from open to closed positions, depending on the test pressurization requirements. The Appendix "C" Pressurization Control System Schematic will more clearly explain this operation.

At the conclusion of the drain operation, a five (5) minute stabilization period was allowed for the currents to come to rest and for the temperatures to stabilize. The recorders were then run for five (5) seconds and then all systems were secured.

The pre-pressurant and pressurant gases were either helium or hydrogen for all test runs. Some of the tests required the same type gas for both operations, while others consisted of both hydrogen and helium. For all helium applications the supporting facility was a tube trailer attached to the pressurization system. The required helium gas temperatures were either ambient or -300°F. Low temperature control was accomplished by the use of a liquid nitrogen heat exchanger. The ambient temperature gas was taken directly from the tube trailer.

The range of hydrogen gas temperatures, being more widely spread, required the use of a temperature controller and six (6) immersion type heaters. Through the use of this system, the liquid hydrogen was converted into the desired operating gas temperature. As with the helium gas, all ambient temperature gas was taken directly from a tube trailer.

Several runs required the application of external heat flux during the testing operation. This phase of the procedure is being covered in paragraph 5.0

FR 13632 A 17.0

built to hold 7000 gallons of liquid hydrogen. It weighs 473 pounds, and has a mass-fraction ratio of 0.897.

The tank was built using annealed sheets of 6Al-4V Eli-grade titanium, supplied by Titanium Metals Corporation of America, to approximately 1/2 standard thickness tolerances. The guaranteed room temperature properties of this sheet are 120,000 psi 0.2% yield strength; 130,000 psi ultimate tensile strength; and 10% elongation.

For fabrication the same jigs and toeling used for aluminum and steel vessels were used for titanium, with minor modifications. All welding was TIG, argon flooded for shielding, no filler, using high heat input and a speed of 12 inches per minute. The entire welding was accomplished by one man in approximately three weeks total time. Welds were x-ray inspected.

The cylinder section was constructed from 0.025 inch sheet, 36×96 inches. Longitudinal welds were staggered every 18 inches around the circumference. No stretch forming was needed. The sheets were simply draped over the wooden form and welded. A wheel type jig was designed to make the circumference welds. A channel was machined in its wall to carry gas to the weld.

The top and bottom closures are hemispheres which transition through a 45° cone to the tank cylinder. The hemispheres consist of 0.018 inch gauge cone trapizoidal sections welded together to form an orange peel pattern. Stress analysis indicated that the individual sections could be tapered in thickness to save weight. They were chemmilled to a taper from 0.018 to 0.014 inch. The sections were then stretch formed to shape and size in a heated dis fixture at about 1300°F, followed by a stress relief at 1000°F and a descaling and pickling. Good joint fit up and uniform clamping were accomplished through magnetic hold-downs under the sheet sections and steel keepers directly above the hold-downs on the top of the sheet. The entire weld zone was shielded with argon.


Titanium has complete compatibility with liquid hydrogen and is noted at temperatures from -423°F to +200°F. The properties of 6Al-4V Titanium are included in Appendices "H."

Following is a sketch of the titanium test tank which is used to demonstrate tank dimensions and skin thickness at various locations. In addition a chart is provided to determine the volume of liquid hydrogen at varous points in the test tank during operating conditions. These volumes were calculated at ambient and at liquid hydrogen temperatures in addition to the operating pressures which were required for this program.

Beech Aircraft Corporation — Environmental Test Laboratories

Document No.	Rev	Page
FR 13632	À.	18.0
lissue Date	Revis	on Dates

11-25-64 A 5/5/65



Tank Dimensions			
Symbol	Inches		
A	46.20		
В	46.20		
C	192.00		
D	92.40		
E	308.10		
F	29.69		
G	66.23		
H	12.50		
I	27.19		
J	12.93		

Skin T	hickness
Symbol	Inches
Sk _l	0.018
Sk ₂	0.014
Ska	0.025
Ski	0.014
Sk ₅	0.018
Sk6	0.025

Figure 1 6A1-4V TITANIUM TEST TANK DIMENSIONS AND SKIN THICKNESS

68 °F

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. Rev Page FR 13632 19.0

issue Date 11-25-64

Revision Dates A 5/5/65

-423	•F

TEMPERATURE, °F

	PRESSURE, PSIA					
Station	12	12	20	30	40	50
308.01 304.01 300.01 296.01 288.01 280.01 276.01 276.01 268.01 261.81 69.81 65.61 41.61 49.61 41.61 40.12 35.00 15.00 15.00 12.93 7.68	7371.80 7362.00 7333.90 7289.10 7229.50 7156.60 7072.50 6978.70 6876.90 6768.90 6656.60 6447.70 904.05 782.46 668.51 504.82 355.04 256.81 188.11 160.84 104.23 41.53 15.97 14.53 5.45 .00	7336.40 7326.70 7298.70 7254.10 7194.80 7122.30 7038.60 6945.20 6843.90 6736.40 6624.60 6446.60 899.71 778.70 665.30 502.40 353.34 264.53 187.21 160.07 103.73 41.33 15.89 14.46 5.42	7351.10 7341.30 7313.30 7268.60 7209.20 7136.50 7052.60 6959.10 6857.60 6749.90 6459.50 901.51 780.26 666.63 503.40 354.04 265.06 187.58 160.39 103.94 41.41 15.92 14.48 5.43	7369.50 7359.70 7359.70 7331.60 7286.80 7227.20 7154.30 7070.30 6976.50 6874.70 6766.80 6654.50 6475.70 903.76 782.21 668.30 504.66 354.93 265,73 188.05 160.79 104.20 41.51 15.96 14.52 5.44 .00	7387.90 7378.10 7349.90 7305.00 7245.30 7172.20 7088.00 6993.90 6891.90 6783.70 6671.10 6491.90 906.02 784.17 669.97 505.92 355.82 266.39 188.52 161.19 104.46 41.62 16.00 14.56 5.46	7406.40 7396550 7368.30 7323.30 7263.40 7190.20 7105.70 7011.40 6909.20 6800.60 6667.60 6508.10 908.29 786.13 671.64 507.19 356.71 267.06 188.99 161.59 104.72 41.72 16.04 14.59 5.47 .00

Note: All volumes in gallons (US).

Boulder atmospheric pressure was taken as 12 PSIA.

Figure 2

7000 GALLON TITANIUM TANK VOLUMES

FR 13632 A 20.0

5.0 EXTERNAL HEATING PROGRAM - The test runs numbers 16, 17, 18, and 22 required the application of external heat flux. The requirements for the first three of these runs was 450 BTU/ft²/hr. Run 22 was made with an application of 900 BTU/ft²/hr.

The radient heat reflector assembly which was used is located inside of the vacuum bell. This assembly is made up of sixteen (16) angular segments, each with its independently programmed Ignitron controller, capable of Q/A, T/T, and aerodynamic heating simulation control modes. These reflector bands are 100 inches in diameter and each is twelve (12) inches wide. Over 3400 clear quartz crystal infrared lamps are used to furnish heat to the test tank. During this program the lamps were four (4) inches from the test tank skin. The heating capability for the system is 3,000 KVA for five (5) minutes or 1,500 KVA continuous operation. The heat imput is controlled by heat rate computers which are located in the remote control room.

For this program the heating rate was determined by measuring the boil-off rate and converting this rate to heat imput.

The heat rate desired was quite low, and control in the Q/A mode was not practical as the curve follower error itself would have resulted in 40% error (or variation between heating tanks). It was determined that the heat imput could be controlled better by temperature sensing and limiting the voltage level so that the heating was nearly constant on any one heat lamp tank.

The temperatures are not that of the titanium tank wall, but that of a ribbon thermocouple element bonded to the tank wall. The thermocouple is electrically and thermally insulated from the tank wall. The thermocouple measures only its own temperature which is a function of the radient heat imput and the thermal conduction of the bonding agent. It is assumed that the emissivity and the bonding is the same on each of the control thermocouples.

The total heat imput is the product of the desired heat imput per square foot and the total sidewall area heated by the lamps. The skirt and transition zones of the test tank were not heated. The total heat imput included the following;

- 1. Radiant and connective heat transfer to the test tank walls.
- 2. Conduction through the skirt and connections from the vacuum bell.
- 3. Boil-off produced within the fill line to the test tank from the FUEL FLOW CONTROL VALVE. (Entirely vacuum jacketed)

The following pages contain calculations and graphical curves which were used to determine the proper applications of heat for this program.

Beech Aircraft Corporation — Environmental Test Laboratories

	Document No.		Rev	Page
	FR	13632	A	21.0
-804	Issue Da	te -64	Revisi	on Dates

Radiant Heat Calculations:

Test Specimen: 7000 gallon titanium tank

Requirements: Radiant heat imput controlled at (a) 450 BTU/Ft2/HR. (b) 900

BTU/Ft2/Hr. on the vertical sidewall of the test tank.

Wall Area:

A =
$$2\pi Rh$$

A = $2\pi (46.2 in)(16 ft)$
A = $2\pi (46.2 in)(194 in)$
A = $92.4\pi (194)$
A = 17925.6π
A = $56286.38 in^2$
A = $391 ft^2$

Heat of Vaporization: (Compendium WADD Technical Report 60-56 Part 1)

$$Q_{VAP} = (214.8 \text{ Cal/Mole})(Mole/2.0160m)(453.60m/#)(1BTU/252Cal)$$

The Specific Heat:

The specific heat (Cp) of hydrogen gas, approximately, from 100°R to 120°R is constant at 2.50 BTU/# R

Total Radiant Heat Imput Rate:

$$Q_{im} = \frac{(450)(391)}{60} = 2933 BTU/Min$$

Heat Imput Calculations v.s. Boiloff:

$$Q_{\underline{im}} = Q_{\underline{VAP}} + Q_{\underline{GBS}} \Delta T$$

$$\dot{m} = \frac{Q_{\underline{im}}}{Q_{\underline{VAP}} + C_{\underline{D}} \Delta T}$$

Assume equilibrium conditions at 15 psia and saturated liquid.

(A) 450 BTU/Ft²/Hr

Requirements:

Wall Area 391 ft

450 BTU/Ft²/Hr

Q_{im} 2933 BTU/Min

Q_{VAP} 192 BTU/#

C_n 2.50 BTU/#°R

For
$$T_v = 95^{\circ}R$$
 $\triangle T = 95-35 = 60^{\circ}R$
 $\frac{1}{192}M = \frac{Q_{im}}{QVAP + C_D \triangle T} = \frac{2933 \ BTU/Min(\#)}{192BTU/\# + 250 \ BTU/\# \circ R(60^{\circ}R)}$

FR 13632 A 22.0

11-25-64

"A" 5/5/65

Reslutant Boiloff = $(8.89 \ \#/\text{Min})(\frac{100 \text{ft}^3}{0.56 \#})(\frac{95}{520}) = 290 \ \text{ft}^3/\text{Min}$

For
$$T_V = 60^{\circ}R$$
 $\triangle T = 25^{\circ}R$

$$\frac{2933 \text{ BTU/Min } (\#)}{192 \text{ BTU/#} + 2.50 \text{BTU/#}^{\circ} \text{R}(25^{\circ} \text{R})} = 11.5 \text{ #/Min}$$

$$(11.5 \#/Min)(\frac{100 \text{ ft}^3}{0.56 \#})(\frac{60}{520}) = 254 \text{ ft}^3/Min}$$

For
$$T_v = 35^{\circ}R$$
 $\triangle T = 0^{\circ}R$

$$(15.05\#/Min)(\frac{100ft^3}{0.56\#})(\frac{35}{520}) = 194 ft^3/Min$$

For
$$T_v = 140^{\circ}R$$
 $\Delta T = 105^{\circ}R$

$$\frac{2933 \text{ BTU/min (#)}}{192 \text{ BTU/#} + 2.50 \text{BTU/#}^{\circ} R(105^{\circ}R)} = 6.45 \text{ #/min}$$

$$(6.45 \#/min)(\frac{100ft^3}{0.56\#})(\frac{140}{520}) = 310 ft^3/min$$

$$Q_{im} = \frac{(900)(391)}{60} = 5865 \text{ BTU/min}$$

For
$$T_v = 35^{\circ}R$$
 $\triangle T = 0^{\circ}R$

$$\frac{5865 \text{ BTU/min } (\#)}{192 \text{ BTU/#} + 2.50 \text{ BTU/#}^{\circ}\text{R} (0^{\circ}\text{R})} = 31.6 \#/\text{min}$$

$$(31.6 \#/min)(\frac{100 \text{ ft}^3}{0.56 \#})(\frac{35}{520}) = 380 \text{ ft}^3/min}$$

For
$$T_v = 60^{\circ}R$$
 $\triangle T = 25^{\circ}R$

$$(23.0 \#/min)(\frac{1.0 \text{ ft}^3}{0.56\#})(\frac{(5.5)}{5.50}) = 474 \text{ ft}^3/min$$

FR 13632 23.0 "A" 5/3/65 11-25-64

A CONTRACTOR

For $T_v = 100^{\circ}R$ $\triangle T = 65^{\circ}R$

$$\triangle T = 65$$
°R

= 16.6 #/min 192 BTU/# + 2.50 BTU/#°R (65°R)

(16.6)
$$(\frac{100 \text{ft}^3}{0.56 \#})(\frac{100}{520}) = 570 \text{ ft}^3/\text{min}$$

For $T_{v} = 140^{\circ}R$ $\triangle T = 105^{\circ}R$

$$\triangle T = 105^{\circ}R$$

= 12.9 #/min 192 BTU/# + 2.50 BTU/#°R (105°R)

$$(12.9 \#/\text{min})(\frac{100 \text{ ft}^3}{0.56 \#})(\frac{140}{520}) = 622 \text{ ft}^3/\text{min}$$

For T = 50,R

$$\triangle T = 15^{\circ}R$$

192 $BTU/\# + 2.50BTU/\#^{\circ}R (15^{\circ}R) = 25.6 \#/min$

$$(25.6 \#/min)(\frac{100ft^3}{0.56\#})(\frac{50}{520}) = 440 ft^3/min$$

For $T_v = 80^{\circ}R$ $\triangle T = 45^{\circ}R$

$$\Delta T = 45$$
°R

= 19.2 #/min192 BTU/# + 2.50BTU/#°R (45°R)


$$(19.2 \, \#/\text{min})(\frac{100 \, \text{ft}^3}{0.56 \, \#})(\frac{80}{520}) = 527 \, \, \text{ft}^3/\text{min}$$



ACTUAL FT3/MINUTE (AT 15.0 PSIA)

Engineering Report

FR 13632 Page 24.0 11-25-64 Ne.ibich A 'A' 5/5/55







Figure 3



FR 13632 26.0

11-25-64

"A" 5/5/65

6.0

LIQUID HYDROGEN GAS DIFFUSER - The pressurization and prepressurization gases comming into the test tank were distributed through a screen diffuser at the top of the test tank. The purpose of this diffuser was to minimize the inlet velocity and disturbances.

The diffuser used for this program was fabricated from 304 stainless steel. The screen was of 26 gage perforated stainless sheet with 0.033 inch diameter holes on 1/18 inch centers. These holes were staggered. Following are the calculations of the diffuser screen openings and the screen hole pattern:

0.033" diameter holes on 1/18" centers staggered.

Area of screen is:
$$A = \pi(R_1 + R_2) \sqrt{h^2 + (R_1 + R_2)^2}$$


 $A = \pi(3.15 + 3.95) \sqrt{(2.0)^2 + (0.80)^2}$
 $A = \pi(7.10) \sqrt{4.64}$
 $A = 48.2 \text{ in}^2$

Total area of openings:

Screen H ole Pattern

$$a = (0.033)^2 \frac{\pi}{4} (14)(16)(48.2)$$

 $a = 9.22 \text{ in}^2$



Diffuser Gas Velocity Cur ve

The following performance curve was made to show the gas velocity versus th mass flow for various temperature pressurant gas. The broken lines were added to show the effect of the higher tank pressure on the mass flow rate. A second scale was included for the mass flow rate of helium gas.

If the assumption is made that the volumetric flow of the pressurant gas must equal the volumetric flow of the liquid, the V* indicates the flow rate for a 40 second drain time.

The formula used fro the plot is: VPA

m = RT

where: m = mass flow rate (pounds/second) V = gas velocity (feet/second) P = static pressure (psia) A = total opening area in screen (in²) R = gas constant (feet/R)T = gas temperature (°R)




Engineering Report


FR 136 32 Page 27.0 11-25-64 Revision A "A" 5/5/05

PERFORMANCE OF DIFFUSER

ON PRESSURIZATION LINE OF THE 7000 GALLON TEST TANK



V* = Velocity of gas with no heat transfer during 400 second drain.
Figure5



FR 13632 A 30.0

also insignificant. Therefore, setting $\mathbb{Q}_{k} = \mathbb{Q}_{r} = 0$ the energy balance equation reduces to:

This equation when written in terms of the temperature difference and assuming the gas and thermocouple parameters are constant shows that the time constant \mathcal{T} , is the time interval required for the junction to respond to 63.2% of the step change in temperature of the media surrounding the couple. The time constant \mathcal{T} , is defined by:

$$\gamma = \frac{\rho_{\mathbf{W}}^{\mathbf{C}_{\mathbf{W}}^{\mathbf{V}}}}{h\mathbf{A}}$$
 where

 $\rho_{\rm W}$ = density of the thermocouple wire

C w = specific heat of the thermocouple wire

V = volume of the thermocouple wire

A = surface area of the thermocouple wire

h = heat transfer coefficient which is further defined as:

$$h = \frac{Nu \ Kg}{D}$$
 where

D = diameter of the wire

Assuming a gas velocity of 5 feet per second and solving the above equation for \mathcal{T} , resulted in time constants of 0.149 for hydrogen gas and 0.817 for nitrogen gas under the conditions of these tests. The actual velocity of the convection currents in the experiment were not measured and the five feet per second was arbitrarily taken in order to define the response parameters.

A step function of temperature in a non-flowing gas requires that the sensor be moved from one temperature region to another or that the sensor be conditioned to an "artificial" temperature in place in the reference gas. It was desired that the ullage gas be as undisturbed as possible and rapid movement between regions would produce both gas velocityand higher than normal initial response. The conditioning may be done by heating or cooling the sensor to a non-equilibrium temperature. This had been done previously by passing a current through the sensor to heat it to an unknown temperature but this involves switching the sensor from a voltage source to a galvanometer and the initial response is lost during the switching time. After consideration of the actual test conditions it was decided to condition the sensor in the saturated liquid, move it to a second position in the warmer ullage gas several inches above the liquid. The stratification was found to be extremely stable in a closed dewar and provided excellant thermal conditions. This also simulated draining of a test liquid to

FR 13632 A 29.0

The same of the sa

11-25- 64

"A" 5/5/65

7.0

FAST RESPONSE THERMOCOUPLE DEVELOPMENT - The thermocouple devel pment program was initiated after an unfruitful search for a suitable thermocouple to measure ullage gas temperatures. The tests required a temperature sensor with a time constant of two seconds or less in hydrogen gas at two atmospheres pressure and cryogenic temperatures. Commerically available sensors of the resistance type were not considered because of the problems introduced by long instrumentation leads (60 feet) and also relatively high mass of the sensor element. Most time response data on temperature sensors is for high heat capacity fluids or for gases at relatively high velocities. Previous work indicated the sensitivity of thermocouples fabricated from small diameter wire and work began to optimize the decign and determine the time constant for these specific conditions.

In order to obtain a fast response from a temperature sensor the heat capacity of the sensing element must be small in relation to the heat transfer to the element. Considering the heat capacity and thermal conductivity of low density gases it is obvious that a sensor element must be made with as little mass as possible. Also, the element must be thermally isolated from its supports. The first of these requirements is met by a small dismeter thermocouple wire as the only mass involved is the mass at the junction of the dissimilar metals. The second requirement is met by making the leads of sufficient length that the heat conduction down the leads is small and assuming that the leads adjacent to the junction are subjected to the same thermal conditions. Other sensors were considered but were found to massive for fast response in low density gases. The mounting requirements were generally massive and too close in thermal proximity to be considered acceptable. Platinum wire resistance probes were considered but require a four-wire lead system to eliminate the error due to lead resistance changes. Also the sensor element "averages" the temperature between the sensor wire supports, which is affected to a considerable degree by heat transfer to the supports. It is obvious that the smallest thermocouple wire used will give the fastest response time. This program was restricted at the onset to a wire size considered large enough to withstand gas velocities up to 30 feet per second.

The rate of response of a thermocouple to a step change in the temperature of the surroundings is essentially a heat transfer problem. The energy balance of the thermocouple junction may be written as:

$$Q_r + Q_k + Q_c = Q_s$$
 where:

 $\mathbf{Q}_{\mathbf{r}}$ is the rate of heat transfer from environment to the junction by means of radiation.

Qk is the rate of conductive heat transfer.

Qc is the rate of convective heat transfer (the junction is assumed to have a finite length, for practical purposes includes segements of the wires of finite length).

Q is the rate at which heat is stored in the junction.

For purposes of simplification we will assume the thermocouple to be cylindrical and of sufficient length that $Q_{\mathbf{k}}$ becomes insignificant. As the absolute temperature of the radiating surfaces are relatively low, $Q_{\mathbf{r}}$ is

Beech Aircraft Corporation — Environmental Test Laboratories

Document No	Rev	Page
F R 13632	A	31.0
lissue Date 11/25/64		n Dates 5/5/65

below a sensor which leaves the sensor wetted and the resultant "drying" time of the sensor was also of interest for this program. After the sensor is moved to the gas space the wire dries off, during which the sensor remains stable at the saturated liquid temperature. The start of warmup is assumed to be the point at which the sensor is no longer cooled by the vaporizing liquid. This point can be used as zero time for the response time in gas only. The response time presented in the data includes this "drying" time which is a function of shape, orientation, and wettability of the couple as well as the heat of vaporization of the liquid.

The cryostat, Figure 9, used for the testing program was a 35-liter Hoffman liquified gas dewar. Extensive modifications were incorporated, which consisted of a movable travel rod, a set of limit switches, four liquid level indicators, and a reference probe. Fixtures were installed to enable fill, vent, and pressurization procedures. A pressure switch was utilized in order to calibrate thermocouples under pressurized conditions.

Using these systems and the supporting test equipment as specified in Figure 10, the apparatus allowed for the fast response testing and calibration of 45 production type sensors in addition to many experimental models.

The procedure used to perform the fast response thermocouple tests was conducted in the following manner. The cryostat was filled with the desired test media until the No. 2 liquid sensor indicated a covered condition. Both the test probe and the reference probe were then immersed in the liquid and allowed a five-minute stabilization period. At the conclusion of five minutes the millivolt output for both probes were read and recorded. Both probes were then raised to a gaseous media and the above stabilization time repeated. The millivolt output of both probes is then again read and recorded. At this time the test probe is lowered into the liquid and allowed five additional minutes to stabilize. The recorder is then started and the test probe is raised to a gaseous media. Each thermocouple was tested for ten runs and the average response time then evaluated.

The first type test probe which was tested was a terlon bracket slingshot thermocouple that NASA has used satisfactorily in liquid oxygen. The response time for these probes was very poor and efforts were concentrated on the fabrication of various other types, each expressing some of the ideas which it was felt might be influencing the response of the thermocouples. Following is a list of the ideas which were derived and tested:

1. The thickness of the teflon slingshot frame.

Results: The mass definitely increased the response time considerably.

2. A slingshot frame fabricated with 18 gauge culcon thermocouple wire.

Results: Much faster response and provided basis for the final production-type probe.

Beech Aircraft Corporation — Environmental Test Laboratories

Page
FR 13632
A 32.0

Issue Date Revision Dates
11/25/64
Rev Page
A 32.0

3. Dimensions of slingshot frame.

Results: One, two and three-inch square frames were tested, with the three-inch model producing a 1.1 average time constant. In comparison the average time constants were 2.0 and 5.0 for the two-inch and one-inch models respectively.

4. Thermocouple junction weld.

Results: The junctions of thermocouples of good response were broken and rewelded. The response time of the re-welded thermocouples was within 2% of the original concept. It was noted the thermocouples couples with excessive wire protruding past the weld provided slow response times.

5. The location of welds on lead wires in relation to the frame.

Results: On the teflon frames, a weld on the outer edge of the probe rather than on the inside edge resulted in a 10% increase in response time.

6. Angle formed by the thermocouple junction.

Results: Thermocouples with the junction formed two inches above the vertical arms of the frame provided considerably faster response than junctions forming a larger angle.

7. Relation of the thermocouple to the horizontal during testing.

Results: Thermocouples tilted to a 30° to 45° angle above the horizontal during testing provided approximately a 25% decrease in response time.

8. Effect of insulation and varnish on the thermocouple wire.

Results: The bare wire provided a much faster response time and further testing revealed that the removal of the insulation from the arms of the frame resulted in an additional 8% to 10% time constant decrease.

9. Cleaning of the thermocouple wire at the junction.

Results: A slight response change was evident. o

10. Travel of probe being removed from liquid.

Results: During testing the probe traveled approximately eleven (11) inches. For the most satisfactory response the time, for the probe to travel this distance, was 0.5 second to 0.9 second.

466

Beech Aircraft Corporation — Environmental Test Laboratories

Document No	Rev	Page
FR 13632	A	33.0
11/25/65		on Dates 5/5/65

At the conclusion of testing the thermocouple, as demonstrated in Figure 8, was selected, based on these results.


FINAL RESULTS

At the conclusion of the test program forty-five (45) thermocouples were extended based on the results of the preliminary models. Response tests and calibrations were made on each of these thermocouples. Calibrations indicated an output versus temperature function very close to that of Powell, Caywood and Bunch although there was a definite offset from the referenced curve. The response of all thermocouples was in excess of 63.2% in two (2) seconds for a change from liquid nitrogen to gas. The time constant, for the response in nitrogen gas (subtracting the "drying" time) is approximately 1.10 seconds. The time constant for the same response in hydrogen gas was approximately second. The sensor in the outflow line was subjected to gas velocities of about fifty (50) feet per second during each of the 35 cool-downs and liquid velocities up to thirty-two (32) feet per second. This sensor failed on the 35th fill operation. All other thermocouples lasted for the duration of the tests.

Further information as to this test program is available in a paper entitled, "Fast Response Thermocouples for Measurement of Temperatures in Cryogenic Gases," by C. C. Robinson, T. Bielawski and A. R. Lowrie. This paper was presented at the National Aeronautics and Space Administration Liquid Hydrogen Symposium in Huntsville, Alabama on January 19 and 20, 1965.

Engineering Report

FR 13632 Page 34.0 11-25-64 Revision A A' 5/5/6.



ΔT = Thermocouple Temperature - Liquid Temperature

Gas Temperature - Liquid Temperature

Figure 7

TYPICAL PRODUCTION THERMOCOUPLE RESPONSE CURVE

BEECH TEST REPORT Document No. Beech Aircraft Corporation — Environmental Test Laboratories FR 13632 Α 35.0 11-25-64 Revision Dates "A" 5/5/65 Welded Junction (ends trimmed) 90° 30 Gage Bare 2.1" Copper Wire 30 Gage Bare Constantan Wire Soldered Junction (Typ. 2 Places) 20 Gage Bare Copper Wire 3" 20 Gage Bare Constantan Wire 1.5" Insulation Removed Above This Point

Figure 8
FAST RESPONSE THERMOCOUPLE

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. Rev Page
FR 13632 A 36,0

lissue Date 11-25-64

Revision Dates
"A" 5/5/65

are an experience of the contract of the contr





Figure 9
THERMOCOUPLE CRYOSTAT

a a Carried to a



166

to the first production of the distribution

Beech Aircraft Corporation — Environmental Test Laboratories

Document No.	Rev	Page
FR 13632	A	38.0
Issue Date 11/25/65		on Dates 5/5/65

8.0

DATA PROGRAM

The data on this test was taken in three separate systems. The first system was sixteen (16) bristol recorders which were used to measure skin temperatures. These thermocouples were patched through a 150° reference oven and wired directly to the recorders. The system is a permanent type and the recorders were built specifically for this purpose. The paper and the recorders were scaled in order to enable data reduction for the program.

A brush events recorder was used to supply the liquid level indications as are called out on the Instrumentation Channel Assignments (Appendix G). In conjunction with the liquid level indicators, a switch trace of FFC (Fuel Flow Control Valve) was provided. The data on this recorder is of the go-nogo type. This is to say that there is either a trace or a blank. A trace is used to indicate a liquid condition while a blank will indicate the area is in a gaseous state. One-tenth (1/10) watt caroon resistors were used to pick up the liquid indication.

The third system was the data computer program which was written to enable Beech Aircraft Corporation to reduce data from the MTA magnetic tape through the use of the G-15D computer. Due to the large amount of time involved to print out this data, it was decided that the information would be transferred to compatible IRM tapes for data reduction on the National Bureau of Standards Digi-Data tape writer. The final typeout was in engineering units and decimal form, while the 98 channels of information were supplied once every 0.5 second.

The ninety-eight channels used in the computer program were deivided as follows:

Channel 1 - Time

The time is provided for relative timekeeping on the data and does not necessarily indicate test time. It runs freely until it reaches approximately 7200 at which time it resets and starts over. This could occur in the middle of a test run. Actual test start is ascertained by valve switch traces.

Channels 2 and 3 - Zero and Full Scale Respectively

The zero and full scale are used for checking the data system. The optimum values for these are zero = 0000 and full scale = 4800. As long as these do vary more than 50 counts there is no data problem.

Channels 4 through 43 - Germanium Thermometers

These channels provide the output from the germanium probes which read directly in degrees Kelvin. The probes had a log/log range between 20°K and 40°K with a separate calibration curve for each probe. The accuracy obtained with curve approximation was ±0.2°K between this range. An over range of a channel is indicated by a minus (-) sign as was the case of the germanium probes when the temperature reached 40°K plus.

Beech Aircraft Corporation — Environmental Test Laboratories

Document No.	Rev	Page
FR 13632	A	35.0
11/25/64	Pevisio	n Dates /5/65

Channels 44 through 83 - Fast Response Thermocouples

These channels provided a range of 20°K to 273°K. The calibration data indicated a ±2°F variation between all forty fast response thermocouples with a response time of less than 0.6 second for 60% of the total change. These probes all used a common calibration curve which was derived from average millivolt readings during individual thermocouple calibration. The accuracy was better than 1% in the range of these probes and since the reference over provided the largest error, yet was the best available, it was decided that a common curve could be used.

Channels 84, 85 and 86 - Temperatures (Linear)

These temperatures were for the buildup, prepressurization, and pressurization-vent gas. They were standard thermocouples with linear relationship to the physical phenomena. The readouts were in degrees Kelvin.

Channels 87, 88 and 89 - Pressures (Linear)

These pressures were for ullage, prepressurization, and pressurization gas. All readouts were in psia.

Channels 90, 91 and 92 - Flow Rates

These channels provided the pre-pressure, pressure-vent, and propellant flow rates. The gaseous flows were supplied in CFM, while the liquid flow was in GPM.

Channels 93, 94 and 95 - Valve Switch Traces

These channels indicated the position of the following valves. A reading of 0 to 75 indicates that the valve is closed, while a 150 to 5000 reading indicates an open position. The valves called out were (PV) pressurization valve, (FFC) fuel flow control valve, and (PPC) pre-pressurization control valve.

Channels 96, 97, 98 and 99 - Liquid Levels

These liquid levels were sensors No. 3, 10, 44 and 43 respectively. Readings of 0 to 75 indicate a liquid condition, while readings of 150 to 5000 indicate that the sensor is in a massous state.

The following is a sample of a printed data sheet demonstrating the reduced data as received from the Digi-Data tape writer.

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. Rev Page
FR 13632 A 40.0

Issue Date Revision Dates
11/25/65 "A" 5/5/65

Time = 1155.2

Zero Reference = 34

Full Scale Reference = 4317

Chnl.	Temp.	Chnl.	Temp.	Canl.	Temp.	Chnl.	Temp.	Chnl.	Temp.
									Property of the second second
4	20.2	5	20.1	6	20.2	7	21.0	ક	20.1
9	20.3	10	20.3	11	20.2	12	20.0	1.3	21.4
14	20.1	15	-+1.0	16	-41.0	17	20.1	18	-41.0
19	-41.0	20	-41.0	21	-41.0	22	-41.0	23	-41.0
24	-41.0	25	-41.0	26	-41.0	27	-41.0	28	-41.0
29	-41.0	30	-41.0	31	-41.0	32	-41.0	33	-41.0
34	-41.0	3 5	-41.0	36 41	-41.0	37	-41.0	38	-AT.O
39 44	-41.0	40	-41.0		-41.0	42	20.1	43	
	20.8	45	20.4	46	20.4	47	20.4	48	2211
49	271.9	50	20.4	51	20.4	52	20.4	53	20.4
54	23.6	55	20.4	56	20.4	57	20.8	58	22.1
59	22.9	60	23.3	61	20.4	62	20.4	63	20.4
64	70.7	65	162.2	66	90.0	67	84.8	6 8	89.2
69	20.4	70	90.5	71	92.4	72	98.5	73	100.2
74	96.4	75	95.0	76	100.2	77	96.4	78	97.5
79	95.8	30	87.6	81	98.1	82	98.3	83	99.9
84	332.7	პ5	105.3	86	113.8	87	3.1	88	9.8
89	8.1	90	1.5	91	388.0	92	1065.0	93	3496.0
94	3542.0	95	46.0	96	120.0	97	4094.0	98	4094.0
99	4094.0				l				a salah s

TEST RESULTS - The following pages contain samplings of data taken from the magnetic tapes and the 30-channel events recordings. (Liquid Levels). While this information does not supply a detailed account of the test run, it does give an indication of some of the required operating parameters. Since data analysis was not required per contractual agreement, this report is not intended for that purpose but the Appendix "K" does include some of the finalized curves and plots which were supplied by MASA after data analysis.

A run sheet has been provided for test run no. 3, which contains only the liquid level sensor response. All data on themagnetic tapes was very erratic due to a timing problem and much of the data is questionable. The prepressurant and pressurant gas temperatures, the operating pressure, and the flow rate of propellant appeared within specifications. A closer analysis of this run could possibly supply some information, but a problem would exist as to just where in the test run the readings occurred.

The data for Test Run No. 8 is included up to the point of the tank rupture. Since this was the first 50 psia test run, there will not be a comparative source of data.

Beech Aircraft Corporation — Environmental Test Laboratories

Document No.	Rev	Page
FR 13632	A	41.0
Issue Date	Revisio	
11/26/64	"A" 5,	/5/65

The following general information is pertinent to this test program:

- (1) The liquid temperatures, which were determined by the germanium thermometers, only indicated between the ranges of 20°K and 40°K. Any temperatures which were warmer than 40°K still indicated this reading.
- (2) The duration of the drain operation was estimated from the pressurization valve switch trace (PV) rather than from the fuel flow control valve (FFC) switch trace. The reason for this being that the response of the FFC valve was slightly slower and for testing purposes both valves were actuated simultaneously.
- (3) The three pressurization transducers varied approximately 2 psi at stabilized conditions. This variation was slightly more during flow conditions.
- (4) At the conclusion of each run the recorders were operated for 5 seconds after a 5-minute stabilization period.
- (5) During Run No. 1 the pressurization and vent gas flow rate range was set at 750-1250 cfm. For all other runs the low range was at zero.
- (6) Liquid level sensors 5 and 7 did not respond properly for any of the test runs.
- (7) All vacuum pressure readings supplied in this program were from visual observation.
- (8) The test tank external skin temperatures were supplied on the Bristol Temperature Recorders. The recorder speed was 2.5 inches per minute. Recordings were supplied to NASA.
- (9) Channels that were disconnected from the commutator were called out on the following run sheets.
- (10) Temperature variations for operating gases could be due to system conditions from the previous run. Several of the runs were conducted in a close proximity of time.

All liquid hydrogen used in this program was guaranteed 95% parahydrogen according to MIL Specifications P27201.

Beech Aircraft Corporation — Environmental Test Laboratories

Document No.	Rev	Page
FR 13632	A	42.0
Issue Date 11-25-64	i .	n Dates /5/65

Run Number 1

Date Test Conducted: 31 July 1964

Pre-Pressurant Gas	0°F Hydrogen
Pressurant Gas	100°F Hydrogen
Operating Pressure	30 psia
Pre-Pressurization Time	61.3 seconds
Stabilization Time	10.5 seconds
Drain Time	363.1 seconds
Ullage (Prior to Pre-	5% (App. 6998.9 Gallons)
Pressurization)	

Pre-Pressurant Gas Temperature

Time	Tempe	Temperature	
T + 0	272.4°K	30.8°F	
T + 10	283.4	50.6°F	
T + 20	287.0	57.1°F	
T + 30	287.0	57.1°F	
T + 40	284.6	52.6°F	
T + 50	283.4	50.6°F	
T + 60	281.0	46.2°F	
T + 61.3	281 .6	47.2°F	

Ullage Pressure at Completion of Pre-Pressurization 30.4 psia

Drain Operation

Time	Pressurant	Temperature		Ullage Pressure
T + 0	198.2°K	-102.9°F	Ü	29.9 psia
T + 10	23 8.2	-30.9°F		30.7
T + 60	262.6	13.0°F		31.3
T + 110	2 63. 6	14.9°F		31.9
T + 160	2 6 4.8	17.0°F		31.5
T + 210	267.4	21.7°F		31.1
T + 260	267.4	21.7°F		31.9
T + 310	269.9	26.2°F		32.2
T + 3 6 0	2 6 9.9	26.2°F		32.2
T + 363.1	269.9	26.2°F		32.2

Sensor Response

Sensor No.	Time (sec.)	Volume (Gal.)	Flow Rate (GPM)
48	Uncovered Prior	to Start of Drain	

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. Rev Page
FR 13632 A 43.0

Issue Date 11-25-64 Revision Dates
"A" 5/5/65

Sensor Response, Continued...

Sensor No.	Time (Sec.)	Volume (Gal.)	Flow Rate (GPM)
48 to 44			
44 to 10	Response was not	Correct	
10 to 3	267.6	4875.3	1093.1 1078.8
3 to empty	65.0	1165.1	1078.8

Ullage Pressure	31.5 psia	
Temperature at Diffused	262.9°K	13.8°F
Temperature at 150" Level	195.3°K	-108.1°F
Temperature at 30.81" Level	20.3°K	-423.1°F
Temperature at Outflow Line	38.2°K	-39 0.9°F

Beech Aircraft Corporation - Environmental Test Laboratories

Page
FR 13632
A
44.0

Issue Date
Revision Dates

11-25-64

Revision Dates
"A" 5/5/65

Run Number 2

Date Test Conducted: 21 August 1964

Pre-Pressurant Gas
Pressurant Gas
O°F Helium
O°F Hydrogen
Barometric Pressure
621.70
Operating Pressure
Pre-Pressurant Time
79.2 seconds
Stabilization Time
3.5 seconds
Drain Time
400.4 seconds
Ullage (Prior to Pre-Pressurization)
5% (App. 6998.9 Gallons)

Pre-Pressurant Gas Temperature

Time	Tempe	rature
T + 0	263.9 °k	15.4°F
T + 10	269.6°k	25.8°F
T + 20 T + 30	263.6°K	14.9°F
T + 40	263.3 ° K 26 7. 1°K	14.5°F 21.1°F
T + 50	258.1 °K	5.0°F
T + 60	243.5 °K	-12.2°F
T + 70	2 62.3°k	12.7°F
T + 79.2	258.7°k	6.1°F

Ullage Pressure at Completion of Pre-Pressurization 32 psia

T + 10 231.9°K -42.0°F T + 34 241.3°K -25.2°F T + 59 244.1°K -20.1°F T + 84 247.1°K -14.7°F T + 109 248.1°K -12.9°F	Pressurant Temperature Ullage Pressure
T + 159 250.2°K -9.2°F T + 209 251.2°K -7.3°F T + 259 249.8°K -9.8°F T + 309 251.2°K -7.3°F T + 359 252.2°K -5.6°F T + 379 250.8°K -8.0°F T + 389 252.5°K -7.8°F	212.7°K -76 6°F 32.1 psia 231.9°K -42.0°F 31.2 psia 241.3°K -25.2°F 31.3 psia 244.1°K -20.1°F 31.0 psia 247.1°K -14.7°F 30.9 psia 248.1°K -12.9°F 32.0 psia 248.1°K -12.9°F 31.3 psia 250.2°K -9.2°F 31.7 psia 251.2°K -7.3°F 31.8 psia 251.2°K -7.3°F 31.3 psia 252.2°K -5.6°F 31.4 psia 252.2°K -8.0°F 31.8 psia 252.5°K -8.0°F 31.8 psia 252.5°K -5.6°F 32.0 psia 251.8°K -7.8°F 31.7 psia

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. Rev Page
FR 13632 A 45.0

Issue Date 11-25-64 Revision Dates
"A" 5/5/65

Run Number 2, Continued...

Sensor Response During Drain

Sensors	Time (Sec.)	Volume (Gal.)	Flow Rate (GPM)
42 to 34	13.1	219.7	1014
34 to 22	19.7	339.9	1103
22 to 10	19.1	348.2	1101
10 to 9	40.1	696.5	1043
9 to 6	119.7	2039.4	1043
6 to 4	79.4	1393.0	1053
4 to 3	40.4	696.4	1038
3 to 2	38.4	695.4	1083
2 to 1	2 3. 8	395.2	9 96
1 to Empty	5.6	74.5	797

Sensors No. 5, 7 and 8 did not respond properly.

Sensor Response During Pre-Pressurization

	Sensor out of Liquid
Sensor No.	(Seconds After Start of Pre-Pressurization)
46	1.6
474	7.2
43	16.2
42	1.0 (After Start of Drain)

Ullage Pressure	30.7	jsia
Temperature at Diffuser	219.6°K	-64.2°F
Temperature at 150" Level	∡92.5°K	-112.3°F
Temperature at 30.81" Level	42.7°K	-332.6°∓
Temperature in Outflow Line	50.7°K	-368.2°F

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. FR 13632	Rev A	Page
		46.0
Issue Date		n Dates
11-25-64	MA" 5/	5/65

RUN NUMBER 3

Date Test Conducted: 20 August 1964

Press.)

Pre-Pressurant Gas O°F Hydrogen Pressurant Gas -100°F Hydrogen Barometric Pressure 617.50 Operating Pressure 30 psia Pre-Pressurization Time 60 seconds Stabilization Time 9.2 seconds Drain Time 399.5 seconds Ullage (Prior to Pre-5% (App. 6998.9 Gallons)

Sensor Response During Drain

Sensors	Time (Sec.)	Volume(Gal.)	Flow Rate (GPM)
34 to 22	18.3	339.9	1084
22 to 10	19.4	348.2	1073
10 to 9	40. 6	696.5	1030
9 to 8	40.0	656.5	985
8 to 6	80.8	1392.9	1030
6 to 4	79.8	1393.0	1050
4 to 3	40.3	696.4	1035
3 to 2	37.9	695.4	1098
2 to 1	23.6	395.2	1010
1 to Empty	5.8	74.5	720

Sensor numbers 5 and 7 not responding properly.

Sensor Response During Pre-Pressurization

Sensor No.	Sensor Out of Liquid (Seconds After Start of Pre-Pressurization		
46	1.4		
<u> </u>	2.7 4.8		
42	7.6		
34	12.2 (After Start of Drain)		

Vacuum Readings

Start of Pre-Pressurization	40	Microns
End of Pre-Pressurization	1500	Microns
T + 6 seconds	2200	Microns
T + 400 seconds	2500	Microne

NOTE: The above data was taken from the Brush Recording. The timing on magnetic tape was not correct and data questionable. Following samples taken during run:

Pre-Press. Gas Temp. 287.6°K 58.1°F Pressurant Temp. 204.1°K -92.4°F

essurant Temp. 204.1 K -92.4°

66

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. Rev Page
FR 13632 A 47.0
Issue Date
11-25-64 Revision Dates
"A" 5/5/65

Run Number 4

Date Test Conducted: 21 August 1964

Pre-Pressurant Gas	O°F Hydrogen
Pressurant Gas	-200°F Hydrogen
Barometric Pressure	621.70
Operating Pressure	30 p sia
Pre-Fressurization Time	64.6 seconds
Stabilization Time	8.9 seconds
Drain Time	403.0 seconds
Ullage (Prior to Pre-Pressuri	zation) 5% (App. 6998.9 Gallons)

Pre-Pressurant Gas Temperature

Time	Temperature	
T + 0	135.4°K	-125.8°F
T + 10	138.0°K	-211.2°F
T + 20	126.5 ° K	-232.0°F
T + 30	127.6°K	-229.8°F
T + 40	137.0°K	-212.9°F
T + 50	139.0°K	-209.2°F
T + 60	136.4°K	-214.0°F
T + 64.6	134.9°K	-216.7°F

Ullage Pressure at Completion of Pre-Pressurization 31.7 psia

Time	Pr es surant °K	Temperature °F	Ullage Pressure psia
T + O	221.5	-60.3	31.9
T + 10	193.5	-111.2	31.4
T + 20	132.5	-131.0	30.7
T + 45	166.3	-160.1	30.7
T + 70	160.4	-170.8	31.2
T + 95	1 5 8 .6	-174.0	31.1
T + 120	154.9	-130.7	31.4
T + 170	154.9	-130.7	3 <u>i</u> .2
T + 220	154.5	-181.4	31.7
T + 270	155.4	-179.8	31.7
T + 320	154.9	-180.7	31.6
T + 370	155.8	-179.1	31.4
T + 388	154.5	-181.4	31.8
T + 398	154.0	-152.0	31.4
T + 1402	155.4	-179.8	31.5
$T + \frac{1}{403.6}$	±53·5	-133.4	31.3

FR 13632

A

RECISION TATE

11-25-64

RECISION TATES

"A" 5/5/65

Run Number 4, Continued...

Sensor Response During Drain

Sensors	Time (Sec.)	Volume (Gal.)	Flow Rate (GPM)
43 to 42 42 to 34 34 to 22 22 to 10 10 to 9 9 to 8 8 to 6 6 to 4 4 to 3 3 to 2 2 to 1 1 to Empty	1.9 12.5 19.3 19.4 39.9 39.9 80.2 80.2 40.8 38.5 24.0	25.5 219.7 339.9 348.2 696.5 656.5 1392.9 1393.0 696.4 695.4 395.2 74.5	807 1062 1060 1080 1045 1038 1044 1044 1021 1082 989 798

Sensors 5 and 7 did not Respond Properly.

Sensor Response During Pre-Pressurization

Sensors Out of Liquid

(Seconds After Start of Pre-Pressurization)

1.7
6.3
1.3 (After Start of Drain)

Vacuum Bell Pressure

Sensor No.

46

44 43

Pre-Pressurization	60	microns
Start of Drain	500	microns
Middle of Drain	500	microns

Ullage Pressure	31.5 pa	s i s
Temperature at Diffuser	143.3°K	-201.4°F
Temperature at 150" Level	140.8°K	-206.0°F
Temperature at 30.81" Level	43.0°K	-382.0°F
Temperature in Outflow Line	51.2 °K	-367.3°F

FR 13632	A	49.0
11-25-64	PEVISION O	ATES

Run Number 5

Date Test Conducted: 22 August 1964

Pre-Pressurant Gas	-300°F Helium
Pressurant Gas	-300°F Hydrogen
Barometric Pressure	620.50
Operating Pressure	30 psia
Pre-Pressurization Time	54.2 seconds
Stabilization Time	12.4 seconds
Drain Time	407.7 seconds
117 3 a.m. / Dud and de m. m.	

Ullage (Prior to Pre-Pressurization) 5% (App. 6998.9 Gallons)

Pre-Pressurant Gas Temperature

	Temperature	
Time	• <u>K</u>	• F
T + 0	259.7	7.9
T + 10	223.0	-58.1
T + 20	198.6	-102.0
T + 30	163.1	-166.0
T + 40	130.2	-225. 1
T + 50	105.3	-269.9
T + 54.2	92.1	- 293.7

Ullage Pressure at Completion of Pre-Pressurization 31.1 psia

Time	Pressurant [°] K	Temperature °F	Ullage Pressure psia
T + 0 T + 10 T + 20 T + 45 T + 70 T + 95 T + 145 T + 195 T + 245 T + 295 T + 345 T + 395 T + 395 T + 406 T + 407.7	198.6 154.0 140.5 117.1 113.7 114.8 110.7 113.1 113.1 110.1 110.7 108.4 110.1	-102.0 -182.3 -206.6 -248.7 -254.8 -252.9 -260.2 -254.8 -256.0 -261.3 -260.3 -261.3	31.7 30.1 30.2 31.0 31.1 30.6 30.6 30.7 30.6 30.7 30.5 30.7

FR 13632 11-25-64 "A" 5/5/65

Sensor Response During Drain

Sensors	Time (Sec.)	Volume (Gal.)	Flow Rate (GPM)
43 to 42	1.8	25 .5	მ 50
42 to 34	.2.6	219 .7	1042
34 to 22	20.0	339.9	1020
22 to 10	19.3	348.2	1015
10 to 9	40.3	696.5	1022
9 to 8	40.5	656.5	972
8 to 6	81.4	1392.9	1025
6 to 4	30 . 8	1393.0	1033
4 to 3	40.8	696.4	1008
3 to 2	38.3	695.4	1082
2 to 1	24.1	39 5.2	979
1 to Empty	6.0	74.5	745

Sensors No. 5 and 7 did not respond properly.

Sensor Response During Pre-Pressurization

Sensor No.	Sensor Out of Liquid (Seconds After Start of Pre-Pressurization)
Sensor No.	(Seconds After Start of Pre-Pressurization)
46	4.5
44	ر 30.5
43	1.3 (after start of drain)

Vacuum Bell Pressure

Start of Pre-Pressurization	340 microns
Start of Drain	475 microns
Middle of Drain	275 microns

After 5 Minute Stabilization

Ullage Pressure	30 .7 p sia	
Temperature at Diffuser	98.∂°ĸ	-281.6°F
Temperature at 150" Level	98.3°K	-281.6°F
Temperature at 30.81" Level	41.6°K	-384.6°F
Temperature in Outflow Line	48.9°K	-371.5°F

Channels Out During Run

1 41 m

FR 13632 A 51.0

11-25-64

"A" 5/5/65

Run Number 6

Date Test Conducted: 21 August 1964

Pre-Pressurant Gas
Pressurant Gas
O'F Helium
O'F Helium

8 arometric Pressure
Operating Pressure
Operating Pressure
Pre-Pressurization time
Stabilization Time
Drain Time
Ullage (Prior to Pre-Press.)

O'F Helium
O'F Heliu

Pre-Pressurant Gas Tempera ture

Temperature Time T + 0279.2 43.1 T + 10279.5 43.6 T + 20279.8 44.1 T + 30280.4 45.1 T + 40279.8 44.1 T + 49.8280.4 45.1

Ullage Pressure at Completion of Pre-Pressurization 31.4 psia

Time	Pressurant *K	Temperature °F	Ullage Pressure psia
TT++356666671 ++356666671 TT+++476671 TT++146677 TT++129666667 TT++129667 TT++129667 TT++129667 TT++129667 TT++129666667 TT++12967 TT++12967 TT++	214.6 221.5 236.3 216.3 226.9 260.4 267.1 270.0 272.5 274.3 276.2 278.0 278.9 280.1 281.7 280.4	-74.8 -60.8 -34.7 -70.7 -51.0 21.2 26.5 31.1 34.2 37.6 40.9 42.6 44.6 45.3	30.9 32.5 33.4 30.2 30.7 31.4 31.3 31.1 31.1 31.2 31.2 30.7 31.2 30.7
T + 402.5	280.7	45.7	30.5

FR 13632 A 52.0

The second secon

Run Number 6, Continued...

Sensor Response During Drain

Sensors	Time (Sec.)	Volume (Gal.)	Flow Rate (GPM)
34 to 22 22 to 10 10 to 9 9 to 8 8 to 6 6 to 4 4 to 3 3 to 2 2 to 1 1 to Empty	19.7 19.6 40.7 40.5 80.7 79.8 40.6 33.5 23.9 5.7	339.9 348.2 696.5 656.5 1392.9 1393.0 696.4 695.4 395.2 74.5	1058 1085 1030 935 1038 1050 1039 1090

Sensors No. 5 and 7 did not respond properly.

Sensor Response During Pre-Pressurization

Sensor Number	Sensor Out of Liquid (Seconds After Start of Pre-Pressur	zation)
44 43 42 34 46	3.4 6.7 30.6 12.8 (after start 0.8 (Prior to sta	of drain)

Vacuum Bell Pressure

Start of Drain 1100 microns T + 200 500 microns

Ullage Pressure	30.9 psis	
Temperature at Diffuser	232.9°K	-40.3°F
Temperature at 150" Level	184.7°K	<i>-</i>
Temperature at 30.81" Level	48.2°K	-372.7°F
Temperature in Outflow Line	55.2°K	-360.1°F

FR 13632 53.0

11-25-64

"A" 5/5/65

Run Number 7

Date Test Conducted: 22 August 1964

Pre-Pressurant Gas	-300°F Helium
Pressurant Gas	-300°F Helium
Baremetric Pressure	619.40
Operating Pressure	30 paia
Pre-Pressurization Time	45.6 seconds
Stabilization Time	20.5 seconds
Drain Time	406.5 seconds
Ullage (Prior to Pre-Press.)	5%

Pre-Pressurant Gas Temperature

	Temperature		
Time	<u>°K</u>	°F	
T + 0	260.4	9.2	
T + 10	2 59.7	8.0	
T + 20	257.1	3.3	
T <u>+</u> 30	255. 8	0.9	
T + 40	253. 8	-2.6	
T + 45.6	254.1	-2.1	

Ullage Pressure at End of Pre-Pressurization 31.4 psia

Time	Pressurant K	Temperature	Ullage Pressure psia
T + 0 T + 2 T + 12 T + 22 T + 42 T + 62 T + 87 T + 112 T + 137 T + 237 T + 237 T + 337 T + 387 T + 397 T + 405	180.9 196.3 215.7 225.5 217.1 215.3 210.5 206.3 202.9 199.0 195.9 191.9 191.9 189.9	-133.9 -106.1 -71.3 -53.6 -68.6 -72.0 -80.6 -88.2 -94.3 -101.4 -106.9 -114.1 -117.7 -117.0 -116.2	30.4 31.0 30.1 29.9 29.5 29.8 30.0 30.4 30.5 30.7 30.9 31.0 31.0 31.0
T + 406.5	189.5	-118.4	30.7

FR **1**3632 54.0

11-25-64

the state of the s

"A" 5/5/65

Run Number 7, Continued ...

Sensor Response During Drain

Sensors	Time (Sec.)	Volume (Gal.)	Flow Rate (GPM)
34 to 22	19.9	339.9	1027
22 to 10	19.6	343.2	1065
10 to 9	40.7	696.5	1025
9 to 8	41.2	656.5	953
8 to 6	81.4	1392.9	1023
6 to 4	81.1	1393.0	1031
4 to 3	41.0	696.4	1018
3 to 2	38.8	695.4	1102
2 to 1	24.3	395.2	971
1 to Empty	5.4	74.5	839

Sensors 5 and 7 did not Respond Properly

Sensor Response During Pre-Pressurization

Sensor

43 42

34

Sensor Out of Liquid (Seconds After Start of Pre-Pressurization)

1.7

20.2

13.1 (After Start of Drain)

Vacuum Bell Pressure

During Drain

T + 132T + 150

T + 200

T + 250

T + 322

T + 400

350 microns

300 microns

250 microns

225 microns

300 microns

400 microns

After 5 Minute Stabili ation

Ullage Pressure 30.5 psia

Temperature at Diffuser 173.6°K -147.0°F Temperature at 150" Level ±53.7°K

-182.8°F Temperature at 30.31" Level 40.4°K -386.3°F Temperature in Outrlow Line 45.0°K -378.5°F

FR 13632 A 55.0

11-25-64 "A" 5/5/65

the same was secured to the contract of the co

Run Number 3

Date Test Conducted: 27 August 1964

Pre-Pressurant Gas	0°F Hydrogen
Pressurant Gas	100°F Hydrogen
Barometric Pressure	617.45
Operating Pressure	50 psia
Pre-Pressurization Time	48.7 seconds
Stabilization Time	7.4 seconds
Drain Time	36.8 seconas
Ullage (Prior to Pre-Press.)	5 %

Pre-Pressurant Gas Temperature

	Temperature	
Time	°K	°F
T + 0	263.0	13.9
T + 10	243.4	-21.4
T + 20	229.1	-47.2
T + 30	211.6	-78.6
T + 40	191.5	-114.8
T + 48.7	177.1	-139.6

Ullage Pressure at Completion of Pre-Pressurization 49.4 psia

	Then a a community	6 m	
Time	rressuran °K	t Temperature	Ullage Pressure
TTMO	<u>_v</u>	°F	
T + 0	245.4	-17.9	47.8
T + 2	222.6	-58.9	5 0.4
T + 4	218.2	-66.7	43.1
T + 6	208.6	-34.0	50.2
T + 8	206.7	-97.4	43.3
T + 10	201.0	-97 ·7	49.7
T + 12	201.4	-96.9	43.3
T + 14	196 .3	-106.1	49.7
T + 16	195.1	-108.3	49.1
T + 18	192.7	-112.7	49.1
T + 20	130.7	-116.2	49.0
T + 22	186.7	-123.7	49.7
T + 24	188.7	-119.9	48.5
T + 26	182.5	-130.9	50.4
T + 30	182.5	-130.9	49.7
T + 32	181.3	-133.2	49.4
T + 3 ¹ +	180.9	-133.9	48.3
T + 35	179.6	-136.9	49.3
T + 36	178.8	-137.7	50.2
T + 36.8	175.4	-143.8	50.3
T + 37.3	176.2	° -142.4	50.1
Tank Rupture	333.6	NG	13.2

FR 13632

56.0

11-25-64

"A" 5/5/65

Run Number 8, Continued...

Sensor Response During Drain

Sensors Time (Sec.)

Volume (Gal.)

Flow Rate (GPM)

34 to 22 22 to Rupture

19.8 7.0

339.9

1030

Sensor 44 out of Liquid 2.9 seconds after start of Pre-Pressurization Sensor 43 out of Liquid 4.2 seconds after start of Pre-Pressurization Sensor 42 out of Liquid 22.2 seconds after start of Pre-Pressurization Sensor 34 out of Liquid 13.2 seconds after start of Drain Sensor 22 out of Liquid 6.0 seconds prior to Rupture Sensor 46 out of Liquid 1.2 seconds Prior to start of Pre-Pressurization

Vacuum Bell Pressure

Start of Pre-Pressurization End of Pre-Pressurization Start of Drain

100 microns 2800 microns

2800 microns

Channels Disconnected from Commutator

13 16

41

43

48

59

Beech Aircraft Corporation — Environmental Test Laboratories

Run Number 11

Date Test Conducted: 22 August 1964

Pre-Pressurant Gas	0°F Hydrogen
Pressurant Gas	100°F Hydrogen
Barometric Pressure	620.20
Operating Pressure	20 psia
Pre-Pressurization Time	52.3 seconds
Stabilization Time	13.0 seconds
Drain Time	421.6 seconds
Ullage (Prior to Pre-Press.)) 5%

Pre-Pressurant Gas Temperature

	Temperature	
Time	<u>°K</u>	°F
T + 0	274.9	3 5. 5
T + 10	270.0	26.5
T + 20	275.9	37.1
T + 30	281.0	46.3
T + 40	285.5	54.4
T + 50	291.1	64.5
T + 52.8	291.7	65.6

Ullage Pressure at Completion of Pre-Pressurization 20.2 psia

Time	Pressurant	Temperature	Ullage Pressure
	[°] K	°F	psia
T + 0 T + 3 T + 13 T + 23 T + 23 T + 63 T + 63 T + 93 T + 143 T + 243 T + 295 T + 343 T + 393 T + 393 T + 418 T + 421.6	174.5 206.3 235.1 245.4 260.1 272.8 281.0 286.7 288.3 283.5 279.5 274.0 266.8 266.2 263.9	-145.4 -36.3 -36.3 -47.9 3.7 31.7 46.2 56.5 60.3 50.8 43.6 33.7 20.7 19.7 15.5	19.7 19.9 19.2 19.4 19.7 19.8 19.7 19.8 19.4 19.5 20.0 19.8

Beech Aircraft Corporation — Environmental Test Laboratories

	**************************************	Rev A	58.0
4	11-25-64	Revisio "A" 5	n Dates /5/65

Run Number 11, Continued...

Sensor Response During Drain

Sensors	Time (Sec.)	Volume (Gal.)	Flow Rate (GPM)
42 to 34 34 to 22 22 to 10 10 to 9 9 to 8 8 to 6 6 to 4 4 to 3 3 to 2 2 to 1 1 to Empty	14.1	219.7	912
	20.2	339.9	963
	19.6	343.2	1 063
	41.2	696.5	1016
	40.5	656.5	902
	81.9	1392.9	1012
	83.5	1393.0	1000
	42.9	696.4	976
	41.5	695.4	1008
	26.7	395.2	8 90
	6.8	74.5	664

Sensors 5 and 7 did not Respond Properly

Sensor Response During Pre-Pressurization

Sens	or	Number

44

43

Sensor out of Liquid Seconds After Start of Pre-Pressurization)

At Start

6.8

2.7 (After Start of Drain)

Vacuum Bell Pressure

Start of Drain Middle of Drain 250 microns

300 microns

After 5 Minute Stabilization

Ullage Pressure 19.4 psia

Temperature at Diffuser 230.3 K -44.9°F

Temperature at 150" Level 173.4°K -147.4°F Temperature at 30.81" Level 41.3°K

-385.2°F Temperature in Outflow Line 51.9°K -366.0°F

Service Control

Beech Aircraft Corporation — Environmental Test Laboratures

Document No.	Rev	Page	•
FR 13632	A	59.0	
11-25-64		on Sales 5/5/65	-

Run Number 12

Date Test Conducted: 22 August 1964

Pre-Pressurant Gas	0°F Hydrogen
Pressurant Gas	-100°F Hydrogen
Barometric Pressure	620.00
Operating Pressure	20 psia
Pre-Pressurizing Time	59.5 seconds
Stabilization Time	8.9 seconds
Drain Time	408.1 seconds
Ullage (Prior to Pre-Press.) 546

Pre-Pressurant Gas Temperature

	Tempe	rature
Time	<u>•K</u>	* <u>F</u>
T + 0	280.4	45.2
T + 10	244.1	-20.0
T + 20	204.5	-91.4
T + 30	178.4	-138.4
T + 40	178.4	-138.4
T + 50	183.8	-123.6
T + 59.5	185.0	-126.0

Ullage Pressure at Completion of Pre-Pressurization 20.8 psia

Time	Pressurant 1	Temperature	Ullage Pressure
	°K	°F	psia
T + 0	185.0	-126.0	20.4
T + 5	196.3	-106.1	20.0
T + 15	201.4	-97.0	20.4
T + 40	201.0	-97.7	19.9
T + 65	201.8	-96.2	20.0
T + 115	202.9	-94.3	20.4
T + 165	204.5	-91.4	20.7
T + 215	204.8	-90.9	20.7
T + 265	204.8	-90.9	20.6
T + 315	205.6	-89.4	20.6
T + 365	206.0	-88.7	20.5
T + 408.1	202.6	-94.8	20.4

Beech Aircraft Corporation - Environmental Test Laboratories

Cocument No.	Rev	Page
FR 13632	A	60.0
Issue Date 11-25-64	Revisio	n Dates 5/5/65

Run Number 12, Continued...

Sensor Response During Drain

Sensors	Time (Sec.)	Volume (Gal.)	Flow Rate (GPM)	
42 to 34 34 to 22 22 to 10 10 to 9 9 to 8 8 to 6 6 to 4 4 to 3 3 to 2 2 to 1 1 to Empty	13.2 19.3 19.7 41.0 40.7 81.3 81.1 40.8 39.0 24.7 6.3	219.7 339.9 343.2 696.5 656.5 1392.9 1393.0 696.4 695.4 395.2 74.5	1000 1055 1052 1018 985 1028 1032 1024 1070 914	

Sensors 5 and 7 did not Respond Properly

Sensors Response During Pre-Pressurization

Sensor Number	Sensor Out of Liquid (Seconds After Start of Pre-Pressurization)
43	1.4
42	1.0 (After Start of Drain)

Vacuum Bell Pressure

Pre-Pres	surization	200 microne
Drain	T + 0 T + 115 T + 150 T + 200 T + 250 T + 280 T + 300 T + 330	200 microns 725 microns 600 microns 450 microns 400 microns 300 microns 275 microns 250 microns 225 microns
	T + 408.1	225 microns

Ullage Pressure	20.4	ps ia
Temperature at Diffuser	179.7°K	-136.0°F
Temperature at 150" Level	155.2°K	-130.0 F
Temperature at 30.81" Level	40.1°K	-387.3°F
Temperature in Outflow Line	49.4°K	-370.6°F

Beech Aircraft Corporation - Environmental Test Laboratories

FR 13632 A

Issue Date Revision Dates
11-25-64 "A" 5/5/65

Run Number 13

Date Test Conducted: 22 August 1964

Pre-Pressurant Gas	O°F Hydrogen
Pressurant Gas	-300°F Hydrogen
Barometric Pressure	619.7
Operating Pressure	20 psia
Pre-Pressurization Time	73.5 seconds
Stabilization Time	9.0 seconds
Drain Time	415.4 seconds
Ullage (Prior to Pre-Press.)	5%

Pre-Pressurant Gas Temperature

	Tempe	rature	
Time	<u>*K</u>	•'}	
T + 0	256.4	2.0	
T + 10	196.2	-106.3	
T + 20	149.2	-190.9	
T + 30	115.3	-252.0	
T + 40	80.1	-315.4	
T + 50	82.3	-311.4	
T + 60	94.0	-290.3	
T-+-70	86.7	-303.4	
T + 73.5	89 .5	-298.4	

Ullage Pressure at Completion of Pre-Pressurization 20.7 psia

Time	Pressurant 1	Temperature F	Ullage Pressure psia
T + 0	175.8	-143.0	20 . 6
T + 3	167.1	-158.7	20 . 7
T + 28	139.5	-208.4	21.0
T + 53	129.2	-226.9	20.3
T + 103	117.7	-247.6	20.7
T + 153	117.i	-248.7	20.3
T + 203	114.8	-252.9	20.8
T + 253	118.2	-246.7	20.1
T + 303	117.1	-248.7	20.1
T + 353	112.5	-257.0	20.6
T + 403	117.1	-243.7	20.4
T + 413	116.5	-249.8	20.6
T + 415.4	117.1	-248.7	20.3

Beech Aircraft Corporation - Environmental Test Laboratories

Document No.	Rev	Page
FR 13632	A	62.0
11-25-64		on Dates 5/5/65

Run Number 13, Continued...

Sensor Number	Time (Sec.)	Volume (Gal.)	Flow Rate (GFM)
43 to 42 42 to 34 34 to 22 22 to 10 10 to 9 9 to 8 8 to 6	2.0 12.9 19.3 19.7 41.3 40.7 81.5	25.5 219.7 339.9 348.2 696.5 656.5	765 1022 1 030 1052 1010 966
6 to 4 4 to 3 3 to 2 2 to 1 1 to Empty	82.3 41.6 40.2 2 5. 5 6.3	1393.0 696.4 695.4 395.2 74.5	1025 1016 1002 1030 927 715

Sensors 5 and 7 did not Respond Properly

Sensor Response During Pre-Pressurization

Sensor Number	Sensor Out of Liquid (Seconds After Start of Pre-Pressurization)
44	0.8
43	1.6 (Arter Start of Drain)
46	8.5 (Before Start of Pre-Press.)

Vacuum Bell Pressure

Pre-Pre	essurization	225 microns
Drain	T + O	250 microns
	T + 50	550 microns
	T + 100	425 microns
	T + 160	325 microns
	T + 270	250 microns
	T + 320	225 microns
	T + 345	200 microns
	T + 415.4	200 microns

Ullage Pressure	20.8	osia
Temperature at Diffuser	104.2°K	-272.1°F
Temperature at 150" Level	104.2°K	-272.1°F
Temperature at 30.81" Level	40.4°K	-386.8°F
Temperature in Outflow Line	46.6°K	-375.6°F

Beech Aircraft Corporation - Environmental Test Laboratories

FR 13632 A 63.0

Issue Date
11-25-64 Revision Dates
11-5/5/65

Run Number 14

Date Test Conducted: 21 August 1964

Pre-Pressurant Gas	O°F H, drogen
Pressurant Gas	-100°F Hydrogen
Barometric Pressure	621.20
Operating Pressure	30 psia
Pre-Pressurization Time	46.4 seconds
Stabilization Time	6.9 seconds
Drain Time	757.7 seconds
Ullage (Prior to Pre-Fress.)	5 %

Pre-Pressurant Gas Temperature

	Temperature	
<u>Time</u>	<u>•</u> K	<u>•</u> F
T + 0	221.5	-60.8
T + 10	173.7	-146.8
T + 20	174.1	-146.1
T + 30	183.8	-128.7
T + 40	136.7	-123.4
T + 46.4	193.5	-111.2

Ullage Pressure at Completion of Pre-Pressurization

31.9 psia

Time	Pressurant	Temperature	Ullage Pressure
	*K	F	psia
T + 0 T + 3 T + 13 T + 31 T + 81 T + 131 T + 181 T + 281 T + 281 T + 331 T + 381 T + 481 T + 531 T + 581 T + 681 T + 681	226.2 219.0 213.1 210.5 207.1 205.6 205.2 205.2 204.1 204.8 204.8 206.0 206.3 205.6 205.6 205.6 205.6	-52.3 -65.3 -76.0 -80.6 -86.7 -89.4 -90.1 -90.1 -90.9 -33.7 -88.3 -39.4 -89.4 -89.4 -88.7	32.2 31.3 32.0 31.6 32.2 31.6 31.8 32.2 31.6 31.7 31.4 32.0 31.5 31.5 31.9
T + 731	206.7	-87.5	31.8
T + 757.7	204.8	-90.9	31.6

Beech Aircraft Corporation — Environmental Test Laboratories

FR 13632 A 64.0

Issue Date Revision Dates
11-25-64 "A" 5/5/65

Run Number 14, Continued ...

Sensor Response During Drain

Sensors	Time (Sec.)	Volume (Gal.)	Flow Rate (GPM)
42 to 34 34 to 22 22 to 10 10 to 9 9 to 8 8 to 6 6 to 5 5 to 4 4 to 3 3 to 2 2 to 1	24.6 37.8 37.1 77.7 75.1 150.8 75.1 75.9 76.5 72.0 44.3	219.7 339.9 343.2 696.5 656.5 696.5 696.5 696.4 695.4 395.2	539 541 563 540 525 530 537 553 547 579
l to Empty	10.2	74.5	443

Sensor No. 7 did not indicate

Sensor Response During Pre-Pressurization

Sensor Number	Sensor Out of Liquid (Seconds After Start of Pre-Pressurization)
46	4.2
44	5.6
43	7.3
42	0.6 (After Start of Drain)

Ullage Pres	sur	9		31.0 psia	
Temperature	at	the	Diffuser	190.0°K	-117.5°F
Temperature	at	the	150" Level	178.2°K	-138.7°F
Temperature	at	the	30.81" Level	41.6°K	-384.6°F
			Outrlow Line	43.2°K	-372.4°F

Document No	Rev	Page
FR 13632	Λ	65.0
11-25-64		or Dates

Rua Number 16

Date Test Conducted: 26 August 1964

Pre-Pressurant Gas	O°F Hydrogen
Pressurant Gas	-300°F Hodrogen
Barometric Pressure	618.00
Operating Pressure	30 os1a
External Heat Flux	450 BTU/Ft ² /Hr
Pre-Pressurization Time	53.8 seconds
Stabilization Time	10.0 seconds
Drain Time	403.6 seconds
Ullage (Prior to Pre-Press.)	5%
Limiter (Voltage)	10%
Heat Setting (Heat Rate Comput	ter)80%
Skin Temperature	-300° F

Pre-Pressurant Gas Temperature

Temperature

Time	³K	°F
T + 0 T + 10 T + 20 T + 30 T + 40 T + 50	237.2 179.9 129.7 92.1 69.3 69.3	-32.5 -139.3 -226.2 -293.7 -334.7
T + 53.8	73.2	-327.9

Ullage Pressure at Completion of Pre-Pressurization 31.2 psia

T1me	Pressurant T °K	emperature F	Uilage Pressure psia
T + 0	222.2	- 59 .5	30.1
T + 5	172.4	-149.2	30.2
T + 25	133.4	-219.3	30.2
T + 45	117.7	-247.8	31.3
T + 75	111.9	-25 8.1	30.5
T + 95	110.7	-260.3	30.9
T + 100	109.0	-263.3	31.0
T + 150	107.2	- 266.6	31.4
T + 200	111.9	-258.1	30.7
T + 250	109 .6	-262.3	31.2
T + 300	110.7	-260.3	30.9
T + 350	108.4	-264.5	31.1
T + 400	111.9	-258. 1	30.7
T + 403.6	108.4	- 264.5	30.9

Beech Aircraft Corporation — Environmental Test Laboratories

FR 13632 A 66.0

Issue Date Revision Dates
11-25-64 "A" 5/5/65

Run Number 16, Continued...

Sensor Response During Drain

Sensors	Time (Sec.)	Volume (Gal.)	Flow Rate (GPM)
34 to 22	19.6	339.9	103 2
22 to 10	20.0	348.2	1043
10 to 9	40.1	6%.5	1037
9 to 8	40.1	6 56 .5	930
8 to 6	80.7	1392.9	1032
6 to 4	80.3	1393.0	10140
4 to 3	40.5	696.4	1038
3 to 2	38.5	6 95.4	1075
2 to 1	25.0	3 9 5 •2	945
l to Empty	6.0	74.5	750

Sensor Response During Pre-Pressurization

	Sensor Out of Liquid
Sensor Number	(Seconds After Start of Pre-Pressurization)
46	1.2
<i>ተ</i> ታ	5.7
43	5.7
42	11.2
34	12.8 (After Start of Drain)

Sensors 5 and 7 did not Respond Properly

Channels Disconnected

10 48 13 59 16 41 43

Vacuum Bell Data

Start of Pre-Pressurization 90			microns
End of Pre-	Pressurization	1750	microns
Drain T	+ 60	22 5 0	microns
T	+ 200	1400	microns
T	+ 300	1200	microns
T	+ 400	1400	microns
After 5 Min	ute Stabilization	100	microns

Ullage Pressure	32.9 psis	1
Temperature at Diffuser	-247.7° F	117.7°K
Temperature at 150" Level	-248.1°F	117.5°K
Temperature at 30.81" Level	-367.3° F	51.2°K
Temperature in Outflow Line	29.4°F	271.6°K

Page Document No. 67.0 FR 13632 Issue Date

11-25-64

"A" 5/5/65

Run Number 17

Date Test Conducted: 25 August 1964

Pre-rressurant Gas	0°F Hydrogen
Pressurant Gas	-200°F Hydrogen
Barometric Pressure	618.00
Operating Pressure	30 psia
External Heat Flux	$450 \text{ BTU/Ft}^2/\text{Hr}$
Pre-Pressurization Time	50.1 seconás
Stabilization Time	7.1 seconás
Drain Time	401.8 seconds
Ullage (Prior to Pre-Press.)	5 %
Limiter (Voltage)	10%
Heat Setting (Heat Rate Computer)	80%
Skin Temperature	-300°F

Pre-Pressurant Gas Temperature

	Tempe	rature
Time	°K	°F.
T + 0	181.7	-132.6
T + 10	153 .5	-183.2
T + 20	125.4	-234.0
T + 30	119 .9	-243.8
T + 40	125.4	-234.0
T + 50.1	134.9	-216.8

Ullage Pressure at Completion of Pre-Pressurization 31.0 psia

Time	Pressurant 'K	Temperature ^F	Ullage Pressure peia
T + O	235.4	-36.0	30.8
T + 3	216.0	-7 0.0	30.0
T + 10	189.5	-118.5	30.5
T + 40	161.3	-169.0	30.3
T + 70	151.6	-136.3	30.6
T + 120	±47.3	-193.6	30.5
T + 170	148.3	-192.7	30.6
T + 220	147.3	-194.5	30.6
T + 270	147.3	-194.5	31.4
T + 320	147.3	-194.5	31.1
T + 370	146.4	-196.1	31.0
T + 400	146.9	- 195.2	3 0.9
T + 401.8	146.9	-195.2	30 .3

Beech Aircraft Corporation — Environmental Test Laboratories

Document No	Pev	Page	_
FR 13632	A		
		1 68.0	
Issue Date	Revision	on Cates	
11-25-64	; # A #	5/5/65	

Run Number 17, Continued...

Sensor Response During Drain

Sensors	Time(Sec.)	Volume (Gal.)	Flow Rate (GPM)
34 to 22 22 to 10 10 to 9 9 to 3 5 to 6 6 to 4 4 to 3 3 to 2	19.8 19.4 40.4 40.1 80.2 79.7 40.3 38.2 24.1	339.9 348.2 696.5 646.5 1392.9 1393.0 696.4 695.4 395.2	1030 1075 1030 985 1045 1063 1035 1087 980
1 to Empty	6.4	74.5	700

Sensors 5 and 7 did not Play Properly

Sensor Response During Pre-Pressurization

Sensor Number	Sensor Out of Liqui (Seconds After Start of Pre-Pr	ld ressurization
46	1.8	14 (14) 14) 14 (14)
44 43	4.1	7
42	7·3 31.4	2 (1.5) 1.5 (1.5)
34	13.2 (After Star	t of Drain)

Channels Disconnected

13	43
16	48
41	

Vacuum Bell Pressure

Start of Pre-Pressurization End of Pre-Pressurization		70 microns 2000 microns
Stabilization		2000 microns
Drain $T + 60$		
		2500 microns
$\cos + \mathbf{T}$		1500 microns
T + 300	Ü	
_		1250 microns
T + 400		1500 microns
After 5 Minute Stabilization		
THE DESCRIPTION		1500 microns

After 5 Minute Stabilization

Ullage Pressure	32.4 psia
Temperature at Diffuser	153.1 °K -174.9°F
Temperature at 150" Level	158.3 °K -174.5°F
Temperature at 30.81" Level	55.2 °K -360.2°F
Temperature at Outflow Line	271.9 °K 29.8 °F

156

Beech Aircraft Corporation — Environmental Test Laboratories

FR 13632 A

| Ssue Date | Revision Dates | 11-25-64 | A" 5/5/65

Run Number 18

Date Test Conducted: 25 August 1964

Pre-Pressurant Gas	0°F Hydrogen
Pressurant Gas	-100°F Hydrogen
Barometric Pressure	621.25
Operating Pressure	
External Heat Flux	30 p sia 450 BTU/Ft²/H r
Voltage Limiter	10%
Heat Rate Computer Time	80 %
Skin Temperature	-300°F
Ullage (Prior to Pre-Press.)	5%
Pre-Pressurization Time	46.6 seconds
Stabilization Time	6.5 seconds
Drain Time	427.4 seconds

Pre-Pressurant Gas Temperature

	Tempe	rature
Time	<u>*K</u>	°F
T + 0	297.7	76.3
T + 10	277.4	39.8
T + 20	243.7	-21.0
T + 30	204.5	-91.5
T + 40	179.2	-137.1
T + 46.6	174.5	-145.6

Ullage Pressure at Completion of Pre-Pressurization 31.5 psia

Time	Pressurant Te	mperature °F	Ullage Pressure psia
T + 0	229.1	-47.2	30 .7
T + 5	219.7	-64.2	29.9
T + 10	210.5	-80.7	31.2
T + 50	198.2	-102.9	30.4
T + 100	198.2	-102.9	30.8
T + 150	197.8	-103.6	30.6
T + 200	197.8	-103.6	31.0
T + 250	198.2	-102.9	30.7
T + 300	197.8	-103.6	30.7
T + 350	199.0	-101.4	30.7
T + 400	196.3	-106.3	31.3
T + 427.4	191.5	-115.0	30.9

Beech Aircraft Corporation — Environmental Test Laboratories

Document No.	Rev	Page 70.0
FR 13632	A	10.0
Issue Date	Revisio	n Dates
11-25-64	1	/5/65

Run Number 18, Continued...

Sensor Response During Drain

Sensors	Time (Sec.)	Volume (Gal.)	Flow Rate (GPM)
34 to 22 22 to 10 10 to 9 9 to 8 8 to 6 6 to 4 4 to 3 3 to 2 2 to 1 1 to Empty	20.1 21.6 44.5 43.8 87.3 87.8 41.6 41.9 26.8 6.4	339.9 345.2 696.5 656.5 1392.9 1393.0 696.4 695.4 395.2 74.5	1030 982 942 905 960 961 1010 1000

Heating applied approximately five (5) minutes prior to pre-pressurization. All sensors except 48 covered at the start of heating. Sensor 34 uncovered 5.6 seconds after start of drain. Sensors 5 and 7 did not respond properly.

Channels Disconnected

13 43 16 48 41

Vacuum Bell Pressure

Start of Pre-Pressurization	70 microns
End of Pre-Pressurization	1250 microns
Stabilization	2000 microns
Drain $T + Q$	2250 microns
T + 60	1750 microns
T + 200	1500 microns
T + 300	1200 microns
T + 400	1050 microns
After 5 Minute Stabilization	1300 microns

After 5 Minute Stabilization

Ullage Pressure	31.4 psia	
Temperature at Diffuser		06.0°F
Temperature at 150" Level		21.1°F
Temperature at 30.81"Level	-	
Temperature in Outflow Line	<u> </u>	93.0°F 22.6°F
	20.4 K -4	22.0 F

Beech Aircraft Corporation — Environmental Test Laboratories

F R 13632 A 71.0

| Issue Date | Revision Dates | 11 -25-64 | "A" 5/5/65

- - 144 Okto

Run Number 22

Date Test Conducted: 26 August 1964

Pre-Pressurant Gas	O°F Hydrogen
Pressurant Gas	-100°F Hydrogen
Barometric Pressure	617.45
Operating Pressure	30 psia
External Heat Flux	900 BTU/Ft ² /Hr
Limiter (Voltage)	13%
Heat Setting (Heat Rate Computer)	90 %
Skin Temperature	-150°F
Ullage (Prior to Pre-Press.)	5 %
Pre-Pressurization Time	70.8 seconds
Stabilization Time	7.0 seconds
Drain Time	402.0 seconds

Pre-Pressurant Gas Temperature

	Tempe	rature
Time	<u>°K</u>	<u>• F</u>
T + 0	26 8.1	22.9
T + 10	234.0	-38. 5
T + 20	201.0	-97.8
T + 30	174.1	-146.2
T + 40	175.0	-144.6
T + 50	183.0	-130.2
T + 60	185.4	-126.0
T + 70	191.9	-114.2
T + 70.8	188.7	-120.0

Ullage Pressure at Completion of Pre-Pressurization 31.0

Drain Operation

Time	Pressurant K	Temperature °F	Ullage Pressure psia
T + 0	234.0	-38.4	30.7
T + 5	22 1.9	-60.2	29. 3
T + 10	216.8	-69.4	30.0
T + 50	203.7	-93.0	31.1
T + 100	204.1	-92.3	30.7
T + 150	20 2. 2	-95.7	30 <i>.</i> 6
T + 200	204.5	-91.6	30.9
T + 250	205.6	- 39.6	30.7
T + 300	204.5	-91.6	31.0
T + 350	206.0	-88.9	30.7
T + 400	20 5. 6	-89.6	31.1
T + 402.0	203.3	-93.7	30.9

Beech Aircraft Corporation — Environmental Test Laboratories

			_
	Document No.	Rev	Page
	FR 13632	A	
4		<u></u>	72.0
		Revisio	n Dates
	11-25-64	.ጣሊህ 🕏	15/65

Run Number 22, Continued...

Sensor Response During Drain

Sensors	Time (Sec.)	Volume (Gal.)	Flow Rate (GIM)
34 to 22 22 to 10 10 to 9 9 to 8 8 to 6 6 to 4 4 to 3 3 to 2 2 to 1 1 to Empty	21.4 19.0 40.2 42.4 80.1 80.0 41.3 40.2 25.0	339.9 348.2 696.5 656.5 1392.9 1393.0 696.4 695.4 395.2	954 1100 1035 926 1042 1042 997 1035 812 812

Sensors 5 and 7 did not Respond Properly

Sensor Response During Pre-Pressurization

Sensor Number	Sensor Out of Liquid (Seconds After Start of Pre-Pressurization)		
46 44 43 42 34	4 4.2 6.1 6.5 (After Start of Drah)		

Channels Disconnected

13	41
16	43
19	48

Vacuum Bell Pressure

Start of Dro Dronners	
Start of Pre-Pressurization	60 microns
End of Pre-Pressurization	1250 microns
Stabilization	
	1250 microns
Drain $T + 60$	1400 microns
T + 200	
· · · · ·	1300 microns
T + 300	1000 microns
T + 400	1750 microns
After 5 Minute Stabilization	
> VITTER OF DIAUTITESTION	1400 microns

After 5 Minute Stabilization

Ullage Pressure	22 0 mada
Temperature at Diffuser	33.0 psia 194.8°K -108.8°F
Temperature at 150" Level	127.7°K -229.6°F
Temperature at 30.81" Level	35.3°K -396.1°F
Temperature in Outflow Line	272.3°K 30.6°F

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. Rev Page
FR 13632 A 73.0

Issue Date 11-25-64 Revision Dates
"A" 5/5/65

The state of the s

APPENDIX A

NASA PRESSURIZATION STUDY RUN SEQUENCE

Page 74.0

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. Rev Page FR 13632 A 74.0 Issue Date Revision Dates

"A" 5/5/65

11-25-64

MASA PRESSURIZATION STUDY RUN SEQUENCE

RUM NO.	COMP. DATE	BAROMETRIC PRESSURE	OPERATING PRESSURE (PSIA)	PRE-PRESSURANT GAS AND TEXT. (°F)	PRESSURANT GAS + TEMF. (°F)	DRAIN TIME (SEC)	EXT HEAT FLUX ETU/FT ² /HOUR
1	July 31	א√יז A	3 0	0° Hydromen	100 ⁰ Hydrosen	Loo	0
3	Aug. 20	7.50 י6	3 0	0° Hydrogen	-100° Hydrogen	1,00	O
Ц	Aug. 21	£21.70	30	0° Hydrogen°	-200° Hydronen	l;00	0
2	Aug. 21	621.70	3 0	O ^O Helium	0° Hydrogen	700	0
14	Aug. 21	621.20	30	0° Hydrogen	-100° Hydrogen	800	0
6	Aug. 21	621.20	3 0	O ^O Helium	0° Helium	1,00	Э
7	Aug. 22	619.40	3 0	-300° Helium	-300° Helium	400	0
5	Aug. 22	620.50	30	-300° Helium	-300° Hydrogen	700	0
11	Aug. 22	620.20	20	O ^O Hydrogen	100° Hydrogen	1,00	0
12	Aug. 22	620.00	20	0° Hydrogen	-100° Hydrogen	400	0
13	Aug. 22	619.70	20	0° Hydrogen	-300° Hydrogen	1,00	0
18	Aur. 25	621.25	30	O ^O Hydrogen	-100° Hydrogen	400	L50
17	Aug. 26	618.00	3 0	0° Hydrogen	-200° Hydrogen	7100	450
16	Aug. 26	618.00	30	0° Eydrogen	-300° Hydrogen	£00	450
22	Aug. 26	617.45	3 0	0° Hydrogen	-100° Hydrogen	1:00	900
8	Aug. 27	617.15	50	0° Hydrogen	190° Hydrogen	T00	0
	A. aller, on a free property of the contract o						
	in majerto e este de maior de la companya de la co						
_			The second secon				
			The second secon				

Beech Aircraft Corporation — Environmental Test Laboratories

AND THE RESERVE OF THE PROPERTY OF THE PROPERT

APPENDIX B

PROPELLANT AND PRESSURIZATION SCHEMATIC

THERMAL TEST FACILITY

Page 76.0

Beech Aircraft Corporation — Environmental Test Laboratories

LINE COMPANY OF THE STATE OF TH

Page 77.0 Rev Page 777.0

FR 13632 A Revision Dates 11-25-64 "A" 5/5/65


GH₂ HE

APPENDIX C

PRESSURIZATION CONTROL SYSTEM SCHEMATIC

Page 73.0

Company of the second of the s



NOMENCIATULE

Pressure Regulator

Heat Exchanger - HE

Pressure Transducer P

Temperature Probe (T)


Three Way Valve - -

Liquid Level Indicator (LL

Solenoid Valve

LN2 Heat Exchanger - ogosso

Be




HEAT TOWER, PROPELIANT AND PRESSURIZATION 12 Supply SYSTEM FR 13632 11-25-64 LN₄ LN_2 Pa, 5 76.0 Bypass Revision A "A" 5/5/05 IN2 Fill HE ROGEN DEWAR NO. 1 FHE LIQUID HYDROGEN DEWAR NO P Vent

Vent HE NHE

HE

LIQUID NITROGEN

DEWAR



Beech Aircraft Corporation — Environmental Test Laboratories


Document No. Rev Page 79.0

FR 13632 A Revision Dates
11-25-64 "A" 5/5/65


APPENDIX D

THERMAL TEST FACILITY PHOTOGRAPHS


Pages 30.0 - 91.0




THERMAL TEST FACILITY DURING OPERATIONS




PROPELLANT FLOW CONTROL SYSTEM




LIQUID HYDROGEN 7000-GALLON STORAGE DEWARS




PRESSURIZATION HEAT EXCHANGER SYSTEM




VACUUM BELL PUMPING SYSTEM



HEATING LAMPS AND REFLECTOR SHIELD DAMAGE




TITANIUM TEST TANK DAMAGE




THE PROPERTY OF THE PROPERTY OF THE PARTY OF


10




DANAGED TATABLE



PRESSURIZATION SYSTEM DAMAGE



THERMAL TEST TOWER



VACUUM BELL COVER DAMAGE

Beech Aircraft Corporation — Environmental Test Laboratories

1	Document No.	Rev	Page
	FR 13632	A	
			92.0
_	Issue Date	Revisio	n Dates
	11-25-64	"A 1	5/5/65

APPENDIX E

TEST EQUIPMENT LIST

Pages 93.0 - 94.0

FR 13632 A 93.0

	TI	7		, .	-	- Ţ -	PN	ИE	N.	Γ															- 1				
Last Calib.	2-6.	79-7	10-63	7 7	77	1 2	30	7-8.	1 2	7.00	7-6	8-6	P. 61.	3	19-9	7.4	120	120	70	7-61	200	7-6		4	X	N/A	2	I	
Calib. Every	را م		12 до.			9		13 m/m		6 по.	1	13 wks	13 whe		6 mo.	13 51/0		1		13 wks		13 wks	W 10	W.A.	N/A	NA.	N/A	N	
Accuracy Required	+ 18		+ 18	N/A	XA		WA	+ 19	N/A	N/A		0,10	0,10	+	+ 1.0	70%	20%	10%	10%	+ 18		· ·	& Chg.	S E O	# 00 C +	+ 18	* 5%	+ 35	
Range, Capacity, Dimensions, Etc.	0-1250 CFM	0-2000 GPM	0-280 CFM	100 channel		30 -430°F to 800	O chamel	5-1500 PSI	0-50 Psia	0-60 Psia	1500F to -3500F	32°	150°	-10 MV to 100.1		0-1000 Microns 0-1000 Microns	1	0-20 MM Hg	0-100 Microns	0-50 PSIA		*	(1) - (Con	ofms +1 ofm	+1.5ohm	1/10 Watt	80 0 - 80	15 - G X A	O-10 and
Serial Number	101/18	4859	10449	108	273	N3 71,9016-	307	R79593	43003	43002	43001	ED300	Н992			138	112	N/A	N/A	8696	5917		to bo	f -	20	N/A	NA		WA
Model or Part No.	FL-64SF303	1-4"x	FI-32SF302	MTA2-902	RE3303-10	1PIG570-21-	MS-1DEX3	GEX206/13	704P2-S391	704P2-5391	152P1 3- PS	RJALBC	c WA	rrup 8686	190	CV1 PV	CV1 PV	ридм	DVSM	PI2357C-350	PA24TC-50	0	ΜΆ			N/A	N/A	436-151-27	N/A
Vendor	Waugh	Cox	Waugh	Control Data	Brush Instr.	Bristol	Int. T&T	Grove	Honeywell	Honeywell	нопеуметт	Jos. Kaye & Co	Thermoelectric	Leeds & Northr	Acrogmag	Hastings	Hastings	Hastings	Hastings	Statham	Statham	Statham	Beech Aircraft	1		Ohmite	Beech Aircraft	Weltron Corp.	West Instr Co.
Name of Equipment	V & P Flowmeter	rrop, flowmeter	Pre-press Flomtr	Magn Tape Recd	Events Recorder	Temp Recorders	Monitor Scope	Dome Controller	Press Controller Honeywell	Controller	1	Ref.	T/C Ref. System	MV Potentiometer Leeds & North	Mg. Amplifiers		Vacuum Gage	Gage	Vacuum Gage	Press Transducer	Press Transducer	Press Transducer	Thermocouples	Temp. Sensors		Carbon Res.	Thermocouples	Switch	Guardsmen Contr.
No.		- 1		1	1			ထ	6	9-		П	1	귀	13	9	17		67	8		2		7			56	\neg	8

FR 13632

11-25-64

-	T:	ES	T	Ε	QI	UII	² №	1E	N	Γ														4 (15.	
Last Calib.		Ž	N/A	N/A	₹	N/A	10-63	10-63	10-63	10-63					and the second second										
Calib. Every	13 vks	N/A	WA	N/A	N/A	N/A	12 mo.	12 то.	i	12 mo.					de commercial de la com										
Accuracy Required	+ 18	8 + 1%	N/A	+ 18	Z.	N/A	+ 1%	<u>:</u>	+ 1%	+ 18					Comment of the Control of the Contro										
Range, Capacity, Dimensions, Etc.	160	175 KVA continuous	N/A	-430°F to 800°F	9500 CFM	1300 CFM	0-2000 GPM	0-2000 GPM	200-2000 GPM	output 0-5-50 MA			And designed on the character of the control of the		Company of the control of the contro	THE CONTRACT OF THE PROPERTY O		0	A TO STANDING CONTROL		7. T.				
Serial Number	N/A	1-16	NA	N/A	7.	C3136-40	N/A	N/A	N/A	N/A									And Street of a spatial death spatial street of the street						
Model or Part No.	2365X	6150A	CC6280-9B	СТР6249	160-16	1721	65PX-0HW	62 4 P	WFB-64-15	WFB305-5-15		The second secon		and and desired the state of th		the country as formation and the country and t			A COLUMN TO THE PARTY OF THE PA						
Vendor	Acragage	Research, Inc	Console " "	=	F.S. Stokes	£	Foxboro	8	8	2			to the state of th		Market All Colonial C				- The second of				The first and th	of which had for page as more in the first the	
Name of Equipment	Pressure Gages	Ignitron Power Controllers	Control	Heat Transfer Computers	Pump	Mech Booster	Indicating Recr.	riow control Indicating Contr.	Turbine Flow Transmitter	Freq. Converter												and the second s	die er etaal tot je je eersteleje beste period je besteleje besteleje	en general de state de la companya d	
E 0 7	ο,	Q	31	33	33	줘	35	%	37	38						e e				- 1	2 Tag				

Beech Aircraft Corporation — Environmental Test Laboratories

PR 13632


Issue Date
11-25-64

Revision Dates
"A" 5/5/65

APPENDIX F


INSTRUMENTATION LOCATIONS


Page 96.0



Notes:

- 1. The symbol \bigcirc designates a fast response copper constantan type thermod
- 2. The symbol () designates a remaining the cometer sensor calibrated from 20 (Liquid Hydrogen Temperature)
- 3. The symbol ∇ designates a 1/10 watt carbon resistor liquid level sensor 4. The symbol \square designates a thermocouple, copper constant an type. (Skir
- 5. Tank Dimensions: 92.4 inch inside diameter; cylinder 192.0 inches long; radius besispherical ends; lower end is tangent to a conical section. The is at the liquid level.





Beech Aircraft Corporation — Environmental Test Laboratories

FR 1363 2

Issue Date
11-25-64

Rev Page
97.0

A

Revision Dates
"A" 5/5/65

APPENDIX G

INSTRUMENTATION CHANNEL ASSIGNMENTS

Page s

5d.0 - 104.0

Beech Aircraft Corporation — Environmental Test Laboratories

PR 13632

11-25-64

"A" 5/5/65

NASA PRESSURIZATION STUDY Instrumentation Channel Assignment

;	rentacton Channet Assignm	enc	
CHANNEL NO.	FUNCTION	TEST PROBE	LOCATION
. 1	Time		
2	Zero Reference		
3	Full Scale Reference		
4	Temperature	Germanium 500	Outflow Line
5	Temperature	Germanium 495	Center Pole 30.81 inch
6	Temperature	Germanium 479	Center Pole 54.81 inch
7	Temperature	Germanium 483	Center Pole 78.81 inch
8	Temperature	Germanium 497	Center Pole 102.81 inch
9	Temperature	Germanium 480	Center Pole 126.81 inch
10	Temperature	Germanium 501	Center Pole 150.81 inch
11	Temperature	Germanium 457	Center Pole 174.81 inch
12	Temperature	Germanium 458	Center Pole 198.81 inch
13	Temperature	Germanium 460	Center Pole 222.81 inch
14	Temperature	Germanium 456	Left Pole 246.81 inch
15	Temperature	Germanium 505	Center Pole 246.81 inch
16	Temperature	Germanium 489	Right Pole 246.81 inch
17	Temperature	Germanium 512	Left Pole 252.81 inch
18	Temp erature	Germanium 490	Center Pole 252.81 inch
19	Temperature	Germanium 455	Right Leg 252.81 inch
20	Temperature	Germanium 511	Left Leg 258.81 inch
21	Temperature	Germanium 488	Center Pole 258.81 inch
2 2	Temperature	Germanium 493	Right Pole 258.81 inch
			-

Beech Aircraft Corporation — Environmental Test Laboratories

FR 13632 A

11-25-64

Revision Dates "A" 5/5/65

NASA PRESSURIZATION STUDY (Cont.)

CHANNEL NO.	FUNCTION	TEST PROBE	LOCATION
•			•
23	Temperature	Germanium 509	Left Pole 262.81 inch
24	Temperature	Germanium 491	Center Pole 262.81 inch
25	Temperature	Germanium 496	Right Pole 262.81 inch
26	Temperature	Germanium 499	Left Pole 266.81 inch
27	Temperature	Germanium 482	Center Pole 266.81 inch
28	Temperature	Germanium 481	Right Pole 266.81 inch
29	Temperature	Germanium 503	Left Pole 270.81 inch
30	Temperature	Germanium 504	Center Pole 270.81 inch
31	Temperature	Germanium 459	Right Pole 270.81 inch
32	Temperature	Germanium 507	Left Pole 274.81 inch
33	Temperature	Germanium 508	Center Pole 274.81 inch
34	Temperature	Germanium 498	Right Pole 274.81 inch
35	Temperature	Germanium 514	Left Pole 278.81 inch
36	Temperature	Germanium 515	Center Pole 278.81 inch
37	Temperature	Germanium 454	Right Pole 278.81 inch
38	Temperature	Germanium 502	Left Pole 280.81 inch
39	Temperature	Germanium 513	Center Pole 280.81 inch
40	Temperature	Germanium 492	Right Leg 280.81 inch
41	Temperature	Germanium 506	Left Pole 282.81 inch
42	Temperature	Germanium 510	Center Pole 282.81 inch
43	Temperature	Germanium 494	Right Pole 282.81 inch
-			
1			

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. Rev Page
FR 13632 A 108.0

11-25-64

Revision Dates
"A" 5/5/65

NASA PRESSURIZATION STUDY (Cont.)

			<u> </u>
CHANNEL NO.	FUNCTION	TEST PROBE	LOCATION
44	Temperature	Thermocouple 7	Outflow Line
45	Temperature	Thermocouple 8	Center Pole 30.81 inch
46	Temperature	Thermocouple 29	Left Pole 54.81 inch
47	Temperature	Thermocouple 45	Center Pole 54.81 inch
48	Temperature	Thermocouple 19	Right Pole 54.81 inch
49	Temperature	Thermocouple 1	Tank Wall 54.81 inch
50	Temperature	Thermocouple 44	Center Pole 78.81 inch
51	Temperature	Thermocouple 30	Left Pole 102.81 inch
52	Temperature	Thermocouple 11	Center Pole 102.81 inch
5 3	Temperature	Thermocouple 20	Right Pole 102.81 inch
54	Temperature	Thermocouple 2	Tank Wall 102.81 inch
55	Temperature	Thermocouple 12	Center Pole 126.81 inch
56	Temperature	Thermocouple 31	Left Pole 150.81 inch
57	Temperature	Thermocouple 13	Center Pole 150.81 inch
58	Temperature	Thermocouple 21	Right Pole 150.81 inch
59	Temperature	Thermocouple 3	Tank Wall 150.81 inch
60	Temperature	Thermocouple 14	Center Pole 174.81 inch
61	Temperature	Thermocouple 32	Left Pole 198.81 inch
62	Temperature	Thermocouple 15	Center Pole 198.81 inch
63	Temperature	Thermocouple 22	Right Pole 198.81 inch
64	Temperature	Thermocouple 4	Tank Wall 198.81 inch
	i	i .	1

Beech Aircraft Corporation — Environmental Test Laboratories

PR 13632

A

186.3

Issue Date 11-25-64

Revision Dates "A" 5/5/65

NASA PRESSURIZATION STUDY (Cont.)

CHANNEL NO.	FUNCTION	TEST PROBE	LOCATION
65	Temperature	Thermocouple 16	Center Pole 222.81 inch
66	Temperature	Thermocouple 33	Left Pole 246.81 inch
67	Temperature	Thermocouple 17	Center Pole 246.81 inch
68	Temperature	Thermocouple 41	Right Pole 246.81 inch
69	Temperature	Thermocouple 5	Tank Wall 246.81 inch
7 0	Temperature	Thermocouple 24	Right Pole 258.81 inch
71	Temperature	Thermocouple 43	Center Pole 270.81 inch
72	Temperature	Thermocouple 34	Left Pole 282.81 inch
73	Temperature	Thermocouple 25	Right Pole 282.81 inch
74	Temperature	Thermocouple 35	Left Pole 287.81 inch
75	Temperature	Thermocouple 26	Right Pole 287.81 inch
76	Temperature	Thermocouple 36	Left Pole 292.81 inch
77	Temperature	Thermocouple 27	Right Pole 292.81 inch
78	Temperature	Thermocouple 37	Left Pole 297.81 inch
79	Temperature	Thermocouple 42	Right Pole 297.81 inch
80	Temperature	Thermocouple 6	Tank Wall 301.81 inch
81	Te mperature	Thermocouple 38	Diffuser
82	Temperature	Thermocouple 39	Diffuser
83	Temperature	Thermocouple 40	Diffuser
84	T2 Buildup Temperature	CU-Con	150° Ref.
_			_

Beech Aircraft Corporation — Environmental Test Laboratories

Document No. Rev Page 18 13632 A

11-25-64

"A" 5/5/65

NASA PRESSURIZATION STUDY (Cont.)

HANNEL NO.	FUNCTION	TEST PROBE	LOCATION	
85	Temp. Tl Pre-Pressure	CU-Con	150° Ref	
86	Temp. T3 Press-Vent	CU-Con	150° Ref.	
87	Pressure Ullage P2	S/N 5979	0 - 50 psia	
88	Pre-Pressure Pl	s/N 611827	0 - 100 psia	
89	Press-Vent P3	s/N 5917	0 - 50 psia	
90	Pre-Press. FMl Flow Rate	s/N 10449	0 - 280 CFM	
91	Press-Vent Flow FM3	s/N 10448	0 - 1125 CFM	
92	Propellant Flow FM2	s/n 4859	0 - 2000 GPM	
93	Switch Trace	Valve PV		
94	Switch Trace	Valve FFC		
95	Switch Trace	Valve PPC		
96	No. 3 Liquid Level	1/10 W. Resistor	78.81 inch	
97	No. 10 Liquid Level	1/10 W. Resistor	246.81 inch	
98	No. 44 Liquid Level	1/10 W. Resistor	280.81 inch	
99	No. 48 Liquid Level	1/10 W. Resistor	282.81 inch	

Beech Aircraft Corporation — Environmental Test Laboratories

FR 13632
Issue Date
11-25-64

NASA PRESSURIZATION STUDY

The following list is the location of the liquid level sensors which will be used to conduct the above-referenced tests. From this list seventeen (17) sensors will be on the Brush recorder and four (4) sensors will be on the monitor scope. All locations are referenced from the bottom edge of the bottom flange on the titanium tank.

Beech Aircraft Corporation — Environmental Test Laboratories

11-25-64

Revision Domes "A" 5/5/65

Sensor	Type Recorder		SENSOR	Temperature	-423 -
No.	Channel Brush Record	Number Monitor Scope	Location	Volume at 12 psia	Volume at 30 pain
12	DI WILL MOUTE	Menizor Beope	(inches) 248.81	(gallons) 6071.1	(gallons) 6098.4
11 10 9 8	Channel 8 Channel 9 Channel 10	Channel 96	247.81 246.81 222.81	6042.1 6013.3 5319.9	6069.4 6040.4 5343.9
7 6 5	Channel 11 Channel 12 Channel 13		198.81 174.81 150.81 126.31	4 6 26.5 3933.2 3239.8	4647.4 3950.9 3254.5
3 2	Channel 14 Channel 15 Channel 16	Channel 95	120.31 102.81 73.31 54.81	2 546.5 18 53.1 11 59.7 4 63. 2	2558.0 1861.5 1165.1 469.7
1	Channel 17		30.81	72.3	74.5

BEECH AIRCHAFT CORPORATION .- EN, HOUSE .TA, TEST , ABORATONE

FR 13632 A 15 4

11-25-64 "A" 5/5/65

APPENDIX H


PROPERTIES OF 6A1-4V TITANIUM

Pages

106.0 - 112.0




FR 13632 Page 106.0 11-25-64 Revision A "A" 5/5/65



THERMAL EXPANSION OF TITANIUM




Page 107.0 11-25-64 Revision A "A" 5/5/65



YOUNGS MODULUS OF SAL-4V TITANIUM




PR 13632 Page 100.0 11-25-64 Revision A "A" 5/5/65



IMPACT ENERGY OF SAL-4V TITANIUM




PR 13632 Page 109.0 11-25-64 Revision A "A" 5/5/65



THERMAL COMDUCTIVITY OF GAL-AV FITANIUM




FR 13632 Page 110.0 11-25-64 Revision A "A" 5/5/65



SPECIFIC HEAT OF 6A1-4V TITANIUM




FR 13632 Page 111.0 11-25-64 Revision A "A" 5/5/65



AVERAGE ELONGATION AND REDUCTION IN AREA OF SA1-4V ANNEALED TITANIUM



FR 18632 Page 112.0 11-25-64 Revision A "A" 5/5/65



AVERAGE TENSILE STRENGTH OF SA1-4V ANNEALED TITANIUM

FR 13632

Α ...

112.0

11-25-64

"A" 5/5/65

0

APPENDIX I

BRISTOL TEMPERATURE RECORDERS


CALIBRATION CURVES

Pages

114.0 - 123.0




FR 13632 - 114.(Page 114.(11-25-64 Revision A : "A" 5/5/65



NO.1 BRISTOL TEMPERATURE RECORDER CALIBRATION CURVE




FR 13632 Page 115.0 11-25-64 Revision A "A" 5/5/65



NO. 2 BRISTOL TEMPERATURE RECORDER CALIBRATION CURVE




FR 13632 Page 116.0 11-25-64 Revision A "A" 5/5/65



NO. 3 TRISTOL TEMPERATURE RECORDER CALIBRATION CURVE




FR 13632 Page 117.0 11-25-64 Revision A "A" 5/5/65



10. A BLISHOL CHREENATION COLORS
CALEBRATION COLOVE




PR 13632 Page 118.0 11-25-64 Revision A "A" 5/5/65



NO. 5 SCHOOL TO P. ATTO & CORDER CALIBRATION CURVE




FR 13632 Page 119.0 11-25-64 Revision A "A" 5/5/65



NO. 6 BRISTOL TEMPERATURE RECORDER CALIBRATION CURVE




FR 13632
Page 120.0
11-25-64
Reviation A
"A" 5/5/65



NO. 7 EXISTOL TEMPERATURE RECORDER CALLERATION CURVE




FR 13632 Page 121.0 11-25-64 Revision A "A" 5/5/65



NO. 8 PAISTOL TEMPERATURE RECORDER CALIBRATION CURVE



FR 13632
Page E2.0
11-25-64
Revision A
"A" 5/5/65




NO. 9 BEISTOL TEMPERATURE RECORDER CALIFORNION OUT TE



FR 13632
Page
11-25-64
Revision A
"A" 5/2/05


0. والما



NO. 10 BRISTOL TEMPERATURE RECORDER CALIBRATION CURVE




Page 124.0 11-25-64 Revision A "A" 5/5/65



NO. 11 BRISTOL TEMPERATURE RECORDER CALIBRATION CURVE

125.0






NO. 13 BRISTOL TEMPERATURE RECORDER CALIBRATION CURVE




PR 13632 Page 126. 11-25-64 Revision A "A" 5/5/65



NO. 13 BRISTOL TEMPERATURE RECORDER CALIBRATION CURVE




FR 13632 Page 127.0 11-25-54 Revision A "A" 5/5/05



NO. 14 BRISTOL TEMPERATURE RECORDED CALIBRATION CURVE



FR 13632 Page 1 11-25-64 Revision A "A" 5/5/65



NO. 15 BRISTOL TEMPERATURE RECORDER CALIBRATION CURVE

EECH AIRCHAFT CORPORATION - EN. H. SONE TA. TEST ANDRAM 4 24

FR 13632 A 129 C

APPENDIX J

FLOWMETER CALIERATION CURVES

Pages

130.0 - _31.0

Outtower P/C

) |-|-

KENOUENS

Beech Alren

Cald by the

Oalidore bed to water

्रि Vis के क्

STOP OF STREET


FR 13632
Fage 130.0
11-25-64
Revision A


POP IN 13 FICKLE TYPE 8 Ž 3 2 Puller 8 8 8 F Tare COX BEALLA TA/7 E & Pan # # # ŧ. N N N ro Total 3076 3071 12263 153,65 ණු ලබ වැටුල් වැටුල් 1227 1227 15509 9150 9152 1887 4,05 Sec. 216 Weigh 1,062 51,062 1 102.352 1 102.352 103, 88 103, 148 103, 158 21.0615 20.257 25.348 184 BS 814 BS 385 SPATAL NO. Volte Volte 000 Ŋ 150 8 50 Temp. Flow 2 P \$ 13 S 8 ূ্ 8 33 4.50 035年7月3 Flowed #30L \$30£ #3Q# 137 Weight 2152 2013 25.12 2152 1076 Lha. \$516.93 1516.93 516.33 15.5 S 258.51 256.46 258.52 256.52 129.36 - CVea ol. 23.774 23.750 23. 3.3 23.752 23.785 Celib. 23.778 23,793 23.643 3 23.755 Factor MIGE PSI P Meter ESP 173 1756.5 Hais ŧ, 34.1 144 日為思 ひと言語 (3) (0) (3) C. 22'5 .324 S.G. Remarks 8.3.9997 11-5-54 9995


COLUMN COLUMN


₩.

Towed Deword










新 大学教徒を

		1111		1	-			1 4 - 1	1						SL				. 11			11:::			
- 1			!!	1176	41.											\sum_{i}					· ·				
	4	65										1		_										_	
జ్ఞ ప్రా	3 5	%			:					· !	ļ														,
FR 13632 Page 133.0	11-25-04 Payer a from	2							: 1112			: 							7	,					
EZ	11-25 Payeta	*						į.		<u></u>															
				1	* . : .									4.1				:			1				. :
						V-:																			
			:							1									***	-		1			
						1				†										1		1.			
		}			111					1															
							-			 :	1									,		-			
				 			 		-	 		1 1 1								 					
					-	-	-	-		-		1										i			-
	-:			1	-	 	 			-	-		 							· · · · · · · · · · · · · · · · · · ·		 	 		-
		† † †		-			-			<u> </u>				 -				- : :		ļ		ļ.,			
	-	 	-	1			-		-	-	+	+ -	-	-		1	-	 -							-
				-	-	ļ	1				-	1	 	; ; ;				11		•					
	-		-		-	-		1	E.	 -	14			· ·		-	-	· 			-	 			
		-	1:		-	H	-	-	SIL	B.	THE COL	tempereture	ļ	L		<u> </u>		ļ	:	†		ļ		<u> </u>	-
		1::	<u> </u>	+	-	de		-	- 69	ensity	日	#3 -	-				-	<u> </u>		!			ļ	1	
aCanaanon	 -	-				Boulder			8		the	be 1			-	1.1				i - 1	ļ	-	-	12	
2	-	K	-	1	-	+		111	1	ne		Ħ			ļ		<u> </u>	<u> </u>		1	-			<u> </u>	-
U Z		F-503	1		ļ	*		<u> </u>	T	F4	إسرد ا						ļ			ļ		1			-
			1		-	d.	ļ	ļ	III III		100 100 100 100 100 100 100 100 100 100	let	ļ	<u> </u>			1	-	-		-		ļ 	-	-
T DESTRUCTION	.	-64-3	-	1961		Cox	_	ļ	On	Du s	prescure measured	T.				-		1 : .	ļ	· · · ·				· · ·	
		40 3	_	-				<u> </u>	ti	72	388	<u>.</u>	-	<u> </u>		<u> </u>		-		: : : 				<u> </u>	_
		E]	ľ,		re.			Dr	9		Ŧ		ļ. Ļ				i:.					ļ	· -	
Į.		io P		8		ပ ပ		!		F 4	d di	E	ļ.					·		<u> </u>		: .+	ļ		
	ł	Model No. FI	,	february,		4		•	10	œ'		LI		İ								: .!:		;	
1	3	de l		1 44		cp			he	دير.	50	pg		1			<u></u>						1		
1 6		9	3	13		e G			E	.	3 . 🗅	4 00	1							1					
KOTH COULT]			. +		For Beech Aircraft			NOTE										1	1					
	3			1		FOI	1	1	0	1.*	-				1		1			;			1	•	
	7		j		1	1				-		-		1		1	1.			. 1					
	+		+-		-j	1	-		+	1	+		1-	+	-	+	1	<u></u>	†- - -	1	-	- 	-	-	+
		†:	-	÷		17	-	 -		-		-		j -	-		+			1		· • ·			
			+:		-		+	1	-	+	-	-	+-	: 	-	1:	+	 				. 1	-		-
	-	1		4	-	-	-	1	-		.			-						. .	1	T.			
			 		-	-			-	-	+	+	+	1	-		+	+	-	+-	-			:	+-
	1		200			1	D -	1	1 :	1	9		1	1	Φ.		1 ::	111	ψ		1		Φ.	. 4-1.01	1



E. J. T.	In berg	A		n Flow udy	Used For Pressurization Flow MASA Pressurization Study	sed For Prassu	i i				C
1000	006	800	200		500	5	4.00	300	200	80	
			•	(ac tual)/min	3	nic Plow V.	Volume trife				
											Ø.
1 1											1
										2	-6
										Ø,	
		2			CSCH.		•				
	on H	the symbol		area of symbol	nin the	*Ith				e G	
	fa11	e density	the sem	When repeat points of the same density fal	n repeat	TE)¥C		Q	1	
									, A		
				2		2.6			2		
	1b/ft2	0.062 1b	7/16	825		0.3428					8
		ton	r position	in regular	Meter			10			
								171	1		

-	17. 1						•			17.		+-		: ·	ļ				-6]					1 ::		1	1.				-
	-		_		L	-		-	1			-	-+-		ļ	<u> </u>	<u> </u>			7	1						1		-	. j 		
	, ,	L .										-										1	<u>. </u>						1			
	ļ				1			-	-			 	-			ļ:	+		-		.		7	<u></u>		+	-	1		_		_
	Page 134.0	11/25/64	100 A (5/65					-	+		: ::	 	-			ļ 	-	- ‡ ·				: . : - j	· · .	B	ļ		- j - j	-	!		:	-
- 3	363	26	1810 7/5	-	- -	-		1	-		.	-	-				-	-		-			! :	-		\ -	-	-	-		<u>.</u>	
	元 2 6 6 7 7 8	7	Hev.			-	· :	1	+					- 			ļ		1				' , 				4		. !			
	<u>ε.</u> Ω	P-1	m, =		-	+		1	+			+-	+			 	-	-	-	i.				ļ		+-		1	- 	<u> </u>	+ =	
					-	-	.	-				-	-				-	;	-	1.				ļ		-	-			. -		
	ļ				1	-		<u> </u>	+			+-	+	•			-	-	+						 	-	; • 	ļ		1	1	
			<u></u>		+			-	-			-	-			1		1 .	+-	-	+				ļ		-				4	7
+					+	+		-	+	- 1	-:-	-	+			-	-	1	+-	+	-				-	-	<u> </u>	-		-	ļ	_
<u> </u>	4								-			-	-	•			1:::	-			-	-	•	-	-						-	
		: 2	1			+	-		-			-	-			 	┼-	-	+	: <u> </u> 	1.			-	+	-	-	-	-	-	1:::	_
					-			1	-			-	- -				-		-		+	· !]	1					
	· :				1:-	-	•••		-	\neg			-		-	-	-	+	+	+-			•			-	-	-	1	1	-	
					· ·			-					; ; r =					+	-		-							-			1:	
						- -		-	$\dot{+}$		2		D	爿	ø		-	1	+		+				 	<u> </u>	-	-	· 		· · · · ·	
Ţ		1			J	+	\$	4				4	B	meter	ţ.			<u>;</u>		-	+		•••		1			 	441			
	o:				.	+		<u>y</u>	-	+	3	density	Btatio	=	T B			<u> </u>	-	+-	+							-	-		-	
	LOWBENSOR											70	- 0		temperature			<u> </u>									ļ.,	- - : .		-	T :	
	園							1	+		med inam	THE.		F	\$				+-	-		-+			l			-	-	 	-	
	8	7	177	- • • •	 	+		•	+		- 9	Ε,	rom		19 E		-:-		.	1	: -				! :-		ļ	-	+		<u></u>	
 -	E	4	7.84		Γ^{-}	\dagger	-	1	+		\$	0	44	red	큠		-	-	+-	1 ::	+	<u> </u>			! !	-		-	+		-	
	3	3	8	ď	100	+	5		-		ر بور	5	CE C	191	*H		2::1:			1	-				! ! i			-				
	A	-- - - - -- - ------	10448		H	+	- d	<u>></u> Н	-			5	H	measur	the in		-	-	 -	-	+-	-			<u>.</u>		<u> </u>	-		-	<u> </u>	
	E	i.	<u></u>	i	5	-	- 5	7 	-	-		<u> </u>	P	g				ļ	-	-	-								:			
	0	¢	N		B	+			-	+		6	Ca	1118	H			<u> </u>			+-	_					-			ļ) •	
 	Ö		긤		ry rear unit,	-	Hoosh Linewoof	<u>4</u>	-	 	4	at 69°P to 72°P	KO	pressure	and from] - [-			·			i. 					
	A	- 4	Ĭ,	-	-	-	-7) U	-		The state of	4	3	7	8							<u>-</u> -					<u> </u>	-	÷	<u> </u>	·	
	CALIBRATION OF NAUGH F	Q	Serial No.	d	H	-	i d	¥	1	-			: -		i		1 <u>.</u> 1 .	:		-		·					, : .					
,	t				 	-	- 4	1 2 4	-		NOTE		+		 ;			 	-		+	;		- :				ļ			· 	
į.	Ü	- !					1	4	+	•• ••	. 22			-		·_ ·_				•	-	. :						-				
						- i -	!	-	-	1.		-		+		· 		!	-	1	+			i			: :	-	÷	+		
						•			-	!-			L.	-		- · · · ·			1	1	-	-					 !	ļ			; :	
- :	-				• ~	-			-	1			1	+					1		-								<u> </u>	-	<u>.</u>	
i.		· -	. +	- 1	F:	-		:-				-		\exists						! -:	:-	- -				-	, , , ,		ļ		-	
		- !.				+			-			1.7 1.1	1.1	+							+			!					 	-3	es,	
			9	, -			!	<u>\$</u>	þ.	- :	-	-:		9		·	1.	ξ	b :		1.	++	004		: .		C	R			, C	1

134-1

, 1	1						P. 1	4 E E E	110.						
C	1000	9		800	700	900		260	48	5	200	CNZ	3	+	
ty sel			+		min	7	י מי לפל ליום		7 1 0	•	•	Odc	00		7 7 1
						1.	.	100	Valuetrin	Valu					
														Ø	
eli ar.														7	
												-		193	#
	· · · · ·										: i .				
	-			1					+				0	7	
	Τ.	1-1-	0	2 points.		:	I agged"	=							
		_		symbol, the			within the	3		•		\$0			i :
	-	£21]	density	the same	2.1		When repeat	E .: E	¥	+		¥			a
				-								Q			
		; !	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				-			- 	1		-		
		3	0.00	1/4	1/1	500	27	03427			Q				
			CPU	<u> </u>	1 4	825	26	12,4			<u> </u>	*****			
				tion	reversed position	in rever	Meter 1			<u>.</u>	Υ -			4	4
			1	-	1	•				51			1		1
5		Donos #	NOT:		A Nozzle	Fressure	Bo	Bun		+ / +					
			STATTON	71		100000000000000000000000000000000000000			+ + +	1			-		11
			Q.	THE CHARLES THE CONTRACT OF COLUMN CO		TUREDTE	CAL						-		
									3					d	100
· · · · · · · · · · · · · · · · · · ·	-						•		Q					+++++++++++++++++++++++++++++++++++++++	<u>. </u>
				- 1											
															1::
	1.1 ******													2	1 .
 -								15				:. 			100
· 	-														
7:-															
T							\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					- -		- -	1::
							7					-	 	-	Ų_
•							1							त्रम्	- 6
	- -		-								- 1			bе	
			+											в	
·	-							· · · · ·			:			Coi	1
· ·						:		-						580	ď
													-		-

Used For Vent Flow WASA Pressurization Study W. O. 82100

Charles

FR 13632 A 135.0.

11-25-64 "A" 5/5/65

APPENDIX K

NASA SUPPLIED TEST CURVES

Page